

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: FBC 7662Dat Workshop m/s Eufie

of _____

Insured: SHC 8573A

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 3k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: 074A

Vehicle: IN / OUT

Veh No: FBC 7662D Yr Regn: 30/6/08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BAJAJ PULSAR c.c. 179Colour Blue A/C: Insured / Std / NI / NASp. Reading Day T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MD2DHDJ22PCJ69112Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 90-80-17R: 120-70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

Rear

R/Bal. 6 mm

L/Bal. mm

L/Bal. mm

D.O.A. 10/3/21D.O.I. 18/3/21

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear, 21 m/s, 0/5 Bal
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Corr unfr. 131-5-2023 L7A #1688nett \$1312L/S \$1300

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

S + RS, SI

Photos

Others

Report Format :

Lump Sum / I.B.I.: (\$)

TOTAL

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

AX14

Name : Parinayakam Muthukumar

Accident Date : 10-Mar-21

Vehicle No : FBC7662D

Bajaj Pulsar
Vehicle Model : DTS-1 180
Manual

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fender <i>ena ✓</i>	\$ 85.00 ✓
2	Fork inner tubes <i>scu X</i>	\$ 290.00 X
2	Fork outer tubes <i>scu X</i>	\$ 250.00 X
1	Fork under bracket <i>17 X</i>	\$ 185.00 X
1	Front brake disc <i>17 X</i>	\$ 135.00 X
1	Front rim shaft <i>17 X</i>	\$ 45.00 X
1	Front rim bearing <i>nm X</i>	\$ 38.00 X
1	Front wheel rim <i>scu X</i>	\$ 320.00 X
1	Top cowling <i>12 X</i>	\$ 135.00 X
1	Windshield <i>17 X</i>	\$ 85.00 X
1	Headlamp <i>scu ✓</i>	\$ 185.00 ✓
2	Front signals <i>n/scu 1pc</i>	\$ 60 120.00 1pc
1	Handle bar <i>scu ✓</i>	\$ 95.00 ✓
2	Handle bar end <i>17 X</i>	\$ 50.00 X
1	Brake lever <i>scu n/c X</i>	\$ 56.00 X
1	Clutch lever <i>scu n/c X</i>	\$ 56.00 X
2	Side mirrors <i>520 —</i>	\$ 110.00 —
1	Fuel tank <i>17 X</i>	\$ 495.00 X
1	Exhaust assy <i>scu —</i>	\$ 585.00 —
1	Exhaust protector <i>scu —</i>	\$ 85.00 —
1	Front footrest - R/H <i>7.12 —</i>	\$ 35.00 —
1	Front footrest bracket - R/H <i>scu —</i>	\$ 50.00 —
1	Brake pedal <i>12 X</i>	\$ 42.00 X
1	Rear fender <i>D.S —</i>	\$ 65.00 —
1	Rear tailboard <i>cu —</i>	\$ 145.00 —
1	Rear taillamp <i>cu —</i>	\$ 180.00 —
1	Rear signal - R/H <i>17 X</i>	\$ 65.00 X
1	Crash bar (1 set) <i>12 X</i>	\$ 150.00 X
1	Rear footrest - R/H <i>scu —</i>	\$ 28.00 —
1	Rear footrest bracket - R/H <i>17 X</i>	\$ 48.00 X
		\$ 4,213.00
	Less 10%	\$ 421.30
		\$ 3,791.70

*not added
18/3/21
2/s #1300/
Teleph. H. H. H. H.
H. H. H. H.*

1708

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : Parinayakam Muthukumar

Accident Date : 10-Mar-21

Vehicle No : FBC7662D

Bajaj Pulsar
Vehicle Model : **DTS-1 180**
Manual

Estimated Repair Costs

Special Net Items

1	Number plate (1 set) <i>sent Rear ID</i>	\$	28.00 <i>10</i>
2	Fork oils <i>11X</i>	\$	30.00 <i>X</i>
2	Fork oil seals <i>11X</i>	\$	56.00 <i>X</i>
1	Steering cone (1 set) <i>11X</i>	\$	75.00 <i>X</i>
1	Rear box <i>SVLX</i>	\$	380.00 <i>X</i>
1	Rear box bracket <i>RX</i>	\$	160.00 <i>X</i>
		\$	729.00

S/No. Labour

1	To provide transport (LOD)	\$	50.00 ✓
2	To check wiring and reset headlamp focusing	\$ <i>11</i>	80.00 <i>X</i>
3	To repair body frame	\$ <i>11</i>	350.00 <i>X</i>
4	To provide labour	\$ <i>300</i>	400.00
		\$	880.00

Grand Total

\$ 5,400.70

Singapore Dollars: Five Thousand Four Hundred and Cents: Seventy only

1897.2
1897

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIKE RECOVERY SERVICE

HP: 8298 6622

Business Reg. No: 201216510M

CASH SALE

NO: 01658

Date: 12/8/21

Particular: _____

Vehicle No: FBC 7662 D

Model No: BAJAJ

From: T.P. POUND TO KAY Fook Si^{na}

To: SROFIA

Time: (Day/Night): _____

Others: _____

CASH \$: 50K

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or others misdemeanour to your vehicle while being towed.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

074A

Vehicle Details

Vehicle No.:

FBC7662D

Vehicle to be Exported:

No

Intended Deregistration Date:

13 Mar 2021

Vehicle Make:

BAJAJ

Vehicle Model:

PULSAR DTS-I 180 MANUAL

Primary Colour:

Blue

Manufacturing Year:

2008

Engine No.:

DJGBPJ28019

Chassis No.:

MD2DHDJZZPCJ69112

Maximum Power Output:

-

Open Market Value:

\$1,387.00

Original Registration Date:

30 Jun 2008

First Registration Date:

30 Jun 2008

Transfer Count:

3

Actual ARF Paid:

\$209.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

31 May 2023

COE Category:

D - Motorcycle

COE Period(Years):

5

PQP Paid:

\$3,830.00

COE Rebate Amount:

\$1,696.00

Total Rebate Amount:

\$1,696.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Mar 2021

OK



Cars & Property

Fashion

Home & Living

Mobiles & Electronics

Hobbies & Games

Jobs & S



Search for an item

📍 All of Singapore

Advertisement

Motorcycles > Motorcycles for Sale > Class 2B



jlpowersports

★★★★★ 34

Chat

Make

Offer

S\$3,000

📄 Share

❤️ 7

Bajaj Pulsar DTSI 200

Contact Seller

Write a custom message...

Hi, is this still available?

Is the price negotiable?

Can I see more photos?

Advertisement



Pioneer Center



Meetup



Used

COE expiry date: 17 Aug 2023 non
renewable

Privacy - Terms