

July

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 17 Mar 2021)
Parts: 143 **HYUNDAI AE IONIQ HEV FL 1.6 DCT (A)** (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHD6990L/17/03/2021 08:56
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER	20.00	0.00	de *459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	de *451.25 FL
3	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	X *394.80 FL nn
4	1		*REAR BUMPER REINFORCRMENT STAY RH	20.00	0.00	X *138.10 FL nn
5	10		*REAR BUMPER CLIPS	20.00	0.00	de *22.00 FL
6	1		*REAR BUMPER FOG LAMP	20.00	0.00	X *201.50 FL nn
7	2		*REAR BUMPER LICENCE LAMP LH/RH	20.00	0.00	X *170.60 FL nn
8	1		*REAR BUMPER REFLECTOR RH	20.00	0.00	de *41.45 FL
9	1		*REAR BUMPER SIDE BRACKET RH	20.00	0.00	X *55.80 FL nn
10	1		*REVERSE SENSOR	0	0.00	X *180.00 FS nn

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,114.90
- List Item Discount on L Items (\$\$)	386.98
Total Parts (\$\$)	1,727.92

ComfortDelGro Engineering Pte Ltd/SHD6990L/17/03/2021 08:56. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Supp Radar sensor RH \$1625.00

2599.10
 20% 2079.28

Estimates on Miscellaneous Items

Particulars	Amount
<u>Miscellaneous Items</u>	
1 OD/TP Case (Insurer)	11.00
Sub Total (S\$)	11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	350 800.00
2	SPRAY PAINTING	New	250 600.00
3	TUFF COATING	New	20 X 60.00
4	CHECK WIRING AND LIGHTING	New	20 X 60.00
5	REMOVE/REFIX REVERSE SENSOR	New	30 60.00
Supp Asset Envr Code \$240 180			
Gross Labour Cost (S\$)			810. 1,580.00

ComfortDelGro Engineering Pte Ltd/SHD6990L/17/03/2021 08:56. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

MIC
Tayfah 97495719
'WP' 17/3/21 @ 4pm
2 days
P/P Resury before paint
Tayfah C/Chantown

2079.28
11
810
\$ 2900.28
2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 18 Mar 2021)**Parts:** 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD6990L/18/03/2021 12:57**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*UNIT ASSY- RADAR CORNER RADAR SENSOR RH	<i>only</i> 20.00	0.00	*1,625.00 FL
						Sub Total (S\$)
						1,625.00
						- List Item Discount on L Items (S\$)
						325.00
						Total Parts (S\$)
						1,300.00

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHD6990L/18/03/2021 12:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

3/18/2021

Repairer Estimates Suppl. #1

18 Mover 1

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 DIAGNOSE AND RESET ERROR CODE

New

180. 240.00

Gross Labour Cost (\$\$)

240.00

ComfortDelGro Engineering Pte Ltd/SHD6990L/18/03/2021 12:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >