

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0221/2021/HR
DATE : 17-Mar-21
WIP : 19577

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 17/3/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Steve,

12 days - ok - Jy - 30 Apr 21

OWNER'S NAME : MR. NEVILLE BERNARD BESTON
ADDRESS : 12 WEST COAST RD
#07-09
SINGAPORE 128042
TELEPHONE : HP +65 91146869
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070145945
VEHICLE NO : **SMV 6317 C**
MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC
MODEL YEAR : 12/10/2020
ENGINE NO : DEM 025294
CHASSIS NO : WAUZZZF43MN000687
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Mar-21
PLACE OF ACCIDENT : ALONG AYE EXPRESSWAY TOWARDS TUAS

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 6317 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO DISMANTLE AND REINSTALL CENTER CONSOLE TO FACILITATE RENEWAL OF FLOOR PAN.	S/N \$	1,800.00	\$	1,800.00
2	TO REMOVE AND REINSTALL REAR AND CENTRE EXHAUST SILENCER. TO ALIGN TO POSITION.	S/N \$	480.00	\$	480.00
3	TO REMOVE AND RENEW FUEL TANK ASSY.	S/N \$	600.00	\$	600.00
4	TO REMOVE AND REINSTALL FRONT SEAT ASSY, REAR SEAT ASSY. BACK REST, ABCD PILLAR TRIMS, SILL TRIMS AND CARPETS.	S/N \$	2,400.00	\$	2,400.00
5	TO CUT OUT AND WELD UNDERCARRIAGE FLOOR PAN.	\$	2,800.00	\$	1,000.00
6	TO RESPRAY UNDERCARRIAGE FLOOR PAN. TO CARRY OUT STONE CHIP TREATMENT, CAVITY PRESERVATION AND JOINT SEALER WORKS.	\$	1,500.00	\$	550.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 9,772.00	\$	7,022.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM SG / CLAIMS@PREMIUMAUTO.COM SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 6317 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	LOWER REINFORCEMENT BAR - LH	1	\$ 49.00	\$ 39.20
2	FLOOR EXTENSION - LH	1	\$ 141.00	\$ 112.80
3	REAR CONNECTING STRUT FOR FLOOR PLATE	1	\$ 53.00	\$ 42.32
4	INNER SOCKET HEAD BOLTS - M10x25	4	\$ 12.00	\$ 8.96
5	HEAT SHIELD FOR CENTER SILENCER	1	\$ 137.00	\$ 109.20
6	FLOOR PAN HEAT SHIELD NUT	5	\$ 7.00	
7	FUEL TANK	1	\$ 5,180.00	\$ 4,144.00
8	FUEL PUMP TANK SEAL RING	1	\$ 40.00	\$ 31.68
9	HEAT SHIELD FOR FUEL TANK	1	\$ 186.00	\$ 148.40
10	CENTRE EXHAUST SILENCER	1	\$ 896.00	\$ 716.40
11	DUAL CLIP FOR EXHAUST SILENCER	1	\$ 59.00	\$ 47.12
12	REAR SILENCER DUAL CLIP	1	\$ 104.00	\$ 82.88
13	REAR UNDERBODY TRIM - LH	1	\$ 133.00	\$ 106.00
14	SUNDRIES		\$ 300.00	\$ 5.60
TOTAL SPARE PARTS		:	\$ 7,297.00	\$ 5,594.56
TOTAL LABOUR CHARGES		:	\$ 9,772.00	\$ 7,022.00
GRAND TOTAL		:	\$ 17,069.00	\$ 12,616.56

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-16/03/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT