



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref:	CS3/SMO20012403/R1Kvf3e 2-1
50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Date:	01/04/2021
			Code:	SMO
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBE 5165A	Veh. Inspected	SJN 3238U
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2003293/MYE	Excess (\$)	0.00
	Assign From	MELVIN YE	Assign Date	18/03/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA JAZZ 1.3L AT	c.c	1339
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	JHMGE68509S209198	Colour	BLUE
	Odometer	305603 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/55 R16	MICHELIN	5 mm
	L/H Front Tyre	185/55 R16	MICHELIN	5 mm
	R/H Rear Tyre	185/55 R16	MICHELIN	5 mm
	L/H Rear Tyre	185/55 R16	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	10/11/2020	Inspection Date	16/11/2020
	Survey held at	ALPHA PERFORMANCE SINGAPORE PTE LTD 48 TOH GUAN ROAD EAST #04-126, ENTERPRISE HUB, SINGAPORE 608586		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	