



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KITTY			Ref: CC4/ASM21003548/Aps3q2 Date: 05/01/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3284C	Veh. Inspected	SLP 1216L	
Policy No.	P2419138	Coverage (\$)	0.00	
Claim No.	S1M035OE	Excess (\$)	0.00	
Assign From		Assign Date	18/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDGG20W30J006816	Colour	GREY	
Odometer	159538 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	PIRELLI	6 mm	
L/H Front Tyre	195/65 R15	PIRELLI	6 mm	
R/H Rear Tyre	195/65 R15	PIRELLI	6 mm	
L/H Rear Tyre	195/65 R15	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/03/2021	Inspection Date	18/03/2021	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	