Kaki Bukit Autohub, 2 Kaki Bukit Ave 2, #01-18 Singapore 417921

Tel No.: +65 6842 0051 / 6744 0510 Fax No.: +65 6741 0510

Company Reg. No.: 200616038C GST Registration No.: 200616038C

Our Ref:

SLP 1216 L

Your ref:

SHA 3284 C

17 March 2021

AXA INSURANCE PTE LTD

BY EMAIL motor.survey@axa.com.sg ONLY

8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811

Attn: Motor Claims Department

Dear Sir/Madam,

DATE OF ACCIDENT: 17 Mar 2021

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

PURSUANT TO PARAGRAPH 2.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We are instructed by SIN TAT TOYS IMPORT & EXPORT TRADING to notify you of a road traffic accident on 17 Mar 2021 at about 11:15 HRS along JUNC OF BUANGKOK DRIVE & HOUGANG AVE 10 involving our client's vehicle SLP 1216 L & SHA 3284 C driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be inform that we don't excess to Merimen System and kindly reply to us by Email / Fax.

Yours faithfully,

