

Surveyor : STEVE LKK
 Claim : AIG OD
 DOA : 18.03.2021
 Emailed : 29.04.2021, 11am
 Date Survey : 18.03.2021

VEHICLE NO : SMN 7331 X
 MODEL : MIT ATTRAGE 1.2
 WIP : 64169

Material	:	\$	<u>5,735.52</u>
Labour	:	\$	<u>7,735.00</u>
Sub-Total	:	\$	<u>13,470.52</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>13,470.52</u>
GST 7%	:	\$	<u>942.94</u>
Grand Total	:	\$	<u>14,413.46</u>
Finalise By/Date	:	<u>LOI / 29/04/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 19/03/2021	<table> <tr> <td>Cust No/Name</td><td>KCV11941/TAN BOON KAI, DARYL (CHEN WENKA</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMN7331X / 27/08/2019</td></tr> <tr> <td>Date In/Mileage</td><td>18/03/2021/ 26280</td></tr> <tr> <td>Chassis/Package</td><td>MMBSTA13AKH001929 /DC17P(F)</td></tr> <tr> <td>Engine No</td><td>3A92UHT2279</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>P57 WINE RED PEARL / BK BLACK</td></tr> </table>	Cust No/Name	KCV11941/TAN BOON KAI, DARYL (CHEN WENKA	Reg No/Reg Date	SMN7331X / 27/08/2019	Date In/Mileage	18/03/2021/ 26280	Chassis/Package	MMBSTA13AKH001929 /DC17P(F)	Engine No	3A92UHT2279	Make/Model	MIT/19MY ATTRAGE 1.2 CVT	Colour/Trim	P57 WINE RED PEARL / BK BLACK
Cust No/Name	KCV11941/TAN BOON KAI, DARYL (CHEN WENKA														
Reg No/Reg Date	SMN7331X / 27/08/2019														
Date In/Mileage	18/03/2021/ 26280														
Chassis/Package	MMBSTA13AKH001929 /DC17P(F)														
Engine No	3A92UHT2279														
Make/Model	MIT/19MY ATTRAGE 1.2 CVT														
Colour/Trim	P57 WINE RED PEARL / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	29/04/2021/ 10:42	BLK	260 / AiTing	64169			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, BOTH REAR FENDER, BOOT, REAR END PANEL, REPAIR REAR SPARE TIRE PANEL, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 3150.00
E PNT98000 RESPRAY ON REAR BUMPER, BOOT, REAR END PANEL, BOTH REAR FENDER, BODY KITS, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 2100.00
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR								✓ 240.00
M SUNDRY APPLY REAR WINDSCREEN GLASS SEALANT								✓ 80.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR								✓ 120.00
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENTS TO FACILITATE REPAIR								✓ 120.00
E PNT88000 REMOVE & INSTALL REAR SEATS TO FACILITATE REPAIR								✓ 120.00
E PNT88000 REMOVE & INSTALL BODY KITS								✓ 80.00
M SUNDRY APPLY SEALANT ON AFFECTED AREAS								✓ 120.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS								✓ 40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY SUPPLY C & C EMBLEM								✓ 40.00
M SUNDRY SUNDRIES								✓ 30.00
A 13900099 REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR								✓ 450.00

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 19/03/2021	<table> <tr> <td>Cust No/Name</td><td>KCV11941/TAN BOON KAI, DARYL (CHEN WENKA</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMN7331X / 27/08/2019</td></tr> <tr> <td>Date In/Mileage</td><td>18/03/2021/ 26280</td></tr> <tr> <td>Chassis/Package</td><td>MMBSTA13AKH001929 /DC17P(F)</td></tr> <tr> <td>Engine No</td><td>3A92UHT2279</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>P57 WINE RED PEARL / BK BLACK</td></tr> </table>	Cust No/Name	KCV11941/TAN BOON KAI, DARYL (CHEN WENKA	Reg No/Reg Date	SMN7331X / 27/08/2019	Date In/Mileage	18/03/2021/ 26280	Chassis/Package	MMBSTA13AKH001929 /DC17P(F)	Engine No	3A92UHT2279	Make/Model	MIT/19MY ATTRAGE 1.2 CVT	Colour/Trim	P57 WINE RED PEARL / BK BLACK
Cust No/Name	KCV11941/TAN BOON KAI, DARYL (CHEN WENKA														
Reg No/Reg Date	SMN7331X / 27/08/2019														
Date In/Mileage	18/03/2021/ 26280														
Chassis/Package	MMBSTA13AKH001929 /DC17P(F)														
Engine No	3A92UHT2279														
Make/Model	MIT/19MY ATTRAGE 1.2 CVT														
Colour/Trim	P57 WINE RED PEARL / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	29/04/2021/ 10:42	BLK	260 / AiTing	64169			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S SPECIALISTJOB								✓ 220.00
SUPPLY ONE SET OF REVERSE SENSOR								
E PNT88000								225.00
REPAIR BOTH REAR CHASSIS → Supp								
E PNT98000								450.00
RESPRAY REAR FLOOR PANEL, & BOTH REAR CHASSIS → Supp								
X	LAMP ASSY,COMB,RR LH				1.00	✓ 337.00	23.00	259.49
X	LAMP ASSY,COMB,RR RH				1.00	✓ 337.00	23.00	259.49
X	BRACKET,RR BUMPER,LH				1.00	✓ 28.00	23.00	21.56
X	BRACKET,RR BUMPER,RH				1.00	✓ 28.00	23.00	21.56
X	FACE,RR BUMPER				1.00	✓ 751.00	23.00	578.27
X	PANEL,QTR,OTR RH				1.00	✓ 767.00	23.00	590.59
X	PANEL,RR END				1.00	✓ 427.00	23.00	328.79
X	STOPPER,WINDSHIELD GLASS				2.00	✓ 3.00	23.00	4.62
X	SPACER,RR WINDOW				3.00	✓ 9.00	23.00	20.79
X	WEATHERSTRIP,TRUNK LID				1.00	✓ 157.00	23.00	120.89
X	PANEL,TRUNK LID				1.00	✓ 795.00	23.00	612.15
X	MARK,THREE-DIA				1.00	✓ 70.00	23.00	53.90
X	MARK,ATTRAGE				1.00	✓ 21.00	23.00	16.17
X	TRIM,RR END				1.00	✓ 66.00	23.00	50.82
X	BODY KITS				1.00	✓ 1643.00	00.00	1643.00
X	PANEL,QTR,OTR LH				1.00	✓ 759.00	23.00	584.43
X	MUD GUARD,RR RH				1.00	✓ 41.00	23.00	31.57
X	LATCH,TRUNK LID				1.00	✓ 218.00	23.00	167.86
X	BOARD,TRUNK ROOM FLOOR				1.00	✓ 195.00	23.00	150.15
X	BUZZER,KEYLESS OPERATIO,RR				1.00	91.00	23.00	70.07
X	GROMMET,RR END TRIM				4.00	3.00	23.00	9.24
X	CLIP,RR END TRIM				4.00	3.00	23.00	9.24
X	CLIP,FR BUMPER				10.00	4.00	23.00	30.80
X	GROMMET,TAIL LAMP				4.00	3.00	23.00	9.24
X	DUCT,RR VENTILATOR				1.00	30.00	23.00	23.10
X	COVER,RR VENTILATOR				1.00	40.00	23.00	30.80
X	CLIP,GEARSHIFT CONTROL LIN				3.00	3.00	23.00	6.93

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 19/03/2021	<table> <tr> <td>Cust No/Name</td><td>KCV11941/TAN BOON KAI, DARYL (CHEN WENKA</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMN7331X / 27/08/2019</td></tr> <tr> <td>Date In/Mileage</td><td>18/03/2021/ 26280</td></tr> <tr> <td>Chassis/Package</td><td>MMBSTA13AKH001929 /DC17P(F)</td></tr> <tr> <td>Engine No</td><td>3A92UHT2279</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>P57 WINE RED PEARL / BK BLACK</td></tr> </table>	Cust No/Name	KCV11941/TAN BOON KAI, DARYL (CHEN WENKA	Reg No/Reg Date	SMN7331X / 27/08/2019	Date In/Mileage	18/03/2021/ 26280	Chassis/Package	MMBSTA13AKH001929 /DC17P(F)	Engine No	3A92UHT2279	Make/Model	MIT/19MY ATTRAGE 1.2 CVT	Colour/Trim	P57 WINE RED PEARL / BK BLACK
Cust No/Name	KCV11941/TAN BOON KAI, DARYL (CHEN WENKA														
Reg No/Reg Date	SMN7331X / 27/08/2019														
Date In/Mileage	18/03/2021/ 26280														
Chassis/Package	MMBSTA13AKH001929 /DC17P(F)														
Engine No	3A92UHT2279														
Make/Model	MIT/19MY ATTRAGE 1.2 CVT														
Colour/Trim	P57 WINE RED PEARL / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	29/04/2021/ 10:42	BLK	260 / AiTing	64169

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X EMBLEM MIVEC TECHNOLOGY → <i>Supp</i> Z TEXT AIG OD CLAIM. DOA : 18.03.21 SURVEYOR STEVE LKK 18.03.21 POLICY NO : 1900151413	1.00	30.00	00.00	30.00
Pro Forma				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	5,735.52		Nett	13,470.52
Labour	7,205.00	7% GST on	13470.52	942.94
Standard Menu	0.00			
Specialist Job	220.00		Total Payable	14,413.46
Diagnostics Job	0.00			
Sundry/Others	310.00			
Total(w/o GST)	13,470.52			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SMN 7331 X

<u>Materials</u>		<u>Cost (\$)</u>
1	Buzzer, keyless operatio, RR	BR 91.00 ✓
2	Grommet ((x4)	nec 12.00 ✓
3	Clips (x4)	nec 12.00 ✓
4	Clips (x10)	nec 40.00 ✓
5	Grommet, tail lamp (x4)	nec 12.00 ✓
6	Duct, RR ventilator	BR 30.00 ✓
7	Cover, RR ventilator	BR 40.00 ✓
8	Clips (x3)	nec 9.00 ✓
Total		246.00
Less 23%		56.58
Total after discount		189.42
9	Emblem Mivec Technology	nec 30.00 ✓
Total Materials		219.42
<u>Labour</u>		<u>Cost (\$)</u>
1	Repair both rear chassis	225.00 ✓
2	Respray rear floor panel, & both rear chassis	450.00 ✓
Total Labour		675.00
Taxable Amount		894.42
7% GST		62.61
Grand total		957.03

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD



LOI AI TING
SENIOR OFFICER - ADMIN
TEL: 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SMN 7331X

WIP: 64169

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Latch Trunk Lid	? / SUPP		/ BT	
2	Board Trunk Room Floor	? / SUPP		/ TAI	
3	Buzzer Keyless	? / SUPP		/ BR	
4	Clip Trim End Panel	? / SUPP		/ nec	
5	Grommet Tail Lamp	? / SUPP		/ nec	
6	Clip Rear Bumper	? / SUPP		/ nec	
7	Cover Rear Ventilator	? / SUPP		/ BR	
8	Rear Ventilator	? / SUPP		/ CRU	
9	Grommet Ventilator	? / SUPP		/ nec	
10	INVEC Logo	? / SUPP		/ nec	
11	Repair Rear Bath Chassis \$925	? / SUPP		/	
12	Respray Rear Floor Panel &	? / SUPP		/	
13	Both Chassis \$450	? / SUPP		/	
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17	Add additional 03 day - Total: 10 day	? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	29/3/21	Steve
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Average 1.2

SURVEYOR: Steve - Luk

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20121-00
V.C.I. Version	B179
Vehicle Information	A13A 2019MY

Reg no 2014 F3312
 2014 very 2015-2016 not to check all
 is and 2015-2016 2016 2016 Done

2021.04.05

All DTCs

2021.04.05

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name				Malfunction Condition	
	MPI/GDI/DIESEL	KOSS_99880010		No DTCs					
	AT/CVT/A-MT/TC-SST	KOSS_99880010		No DTCs					
	4WS/Electric Power Steering	KOSS_99880010		No DTCs					
	ABS/ASC/ASTC/WSS	KOSS_99880010		No DTCs					
	SRS-AIR BAG	KOSS_99880010		No DTCs					
	Air Conditioner	KOSS_99880010		No DTCs					
	ETACS	KOSS_99880010		No DTCs					
	Meter	KOSS_99880010		No DTCs					
	Steering Angle Sensor	KOSS_99880010		Non-target System					
	KOS/OSS/IMMO/Keyless (with KOS)	KOSS_99880010		No DTCs					