

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte.	Cust No/Name	KCV11941/TAN BOON KAI, DARYL (CHEN WENKA			
Ltd.	Reg No/Reg Date				
MOTOR CLAIM DEPT	Date In/Mileage	18/03/2021/ 0			
78 SHENTON WAY #09-16 AIG BUILDING	Chassis No	MMBSTA13AKH001929			
SINGAPORE 079120	Engine No	3A92UHT2279			
Contact No 6419 1892	Make/Model	MIT/19MY ATTRAGE 1.2 CVT			
	Colour/Trim	P57 WINE RED PEARL / BK BLACK			

Account No	Terms	Date/Time Printe	d CSE	Operator		WIP No		
KAX00008	Credit	18/03/2021/ 13	:28 QUK	282 / Kevin Leong		64169		
		Description of 0	Boods / Service	ces	Qty	Unit Price	Disc%	Amount
AFFECTED	AREA			ND PANEL, BODY KIT &				3600.00
E PNT98000 PAINT WO	RK ON REA	ARE TYRE PANEL AR BUMPER, BOOT, & BODY KIT		NDER SPARE TYRE PANEL,				2450.00
E PNT88000			GLASS FOR F	ACILITATE REPAIR				240.00
M SUNDRY		EN SEALANT			,			80.00
E PNT88000		REAR PARKING AS	sis esti	rimasi	70	2)		120.00
E PNT88000		ALL REAR BOOT CO	J CO L	S [] [] [] [] [] [] [] [] [] [] [] [] []	76	9		120.00
E PNT88000 TO REMOV	E & INSTA	ALL REAR SEAT FO	R FACILITATE	REPAIR				120.0
	E & INSTA	ALL BODY KIT						80.0
	SEALANT	ON AFFECTED ARE	A					120.0
1 SUNDRY PERFORM	RUST PREV	ENTION						80.0
	RING & CH	MASSIS ELECTRICA	L SYSTEM					30.0
A 10028901 TO CARRY USING HI		NOSTIC CHECK US	ING HI-SCAN	PRO TEST				120.0
1 SUNDRY TO SUPPL								220.0
1 SUNDRY TO SUPPL	Y 'MIVEC'	EMBLEM						50.0
M SUNDRY								50.0

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	KCV11941/TAN BOON KAI, DARYL (CHEN WENKA		
Ltd.	Reg No/Reg Date	SMN7331X / 27/08/201		
MOTOR CLAIM DEPT	Date In/Mileage	18/03/2021/ 0		
78 SHENTON WAY #09-16 AIG BUILDING	Chassis No	MMBSTA13AKH001929		
SINGAPORE 079120	Engine No	3A92UHT2279		
Contact No 6419 1892	Make/Model	MIT/19MY ATTRAGE 1.2 CVT		
	Colour/Trim	P57 WINE RED PEARL / BK BLACK		

Account No	Terms	Date/Time F	Printed	CSE	Operator		WIP No		
KAX00008	Credit	18/03/2021	/ 13:28	QUK	282 / Kevin Leong	William Control Control	64169		
		The second secon	n of Good	s / Services		Qty	Unit Price	Disc%	Amount
	Y'C & C'	EMBLEM							
M SUNDRY SUNDRIES									50.00
						1 00			
M LAMP ASS	SY,COMB,RR					1.00	337.00		259.49
	SY,LICENSE					1.00	337.00		259.49
M REFLECTO		PLATE				1.00		23.00	39.27
M REFLECTO						1.00		23.00	17.71
	RR BUMPER) I L				1.00		23.00	17.71
	RR BUMPER					1.00		23.00	21.56
M FACE, RR		1171 و١				1.00		23.00	21.56
	R,OTR RH			\sim L	lma'	T1.00	751.00		578.27
	COMB LAM	ND HSC DH	— (271	100191	1.00		23.00	590.59
	COMB LAM			2) [[4.60		23.00	46.20
M PANEL, RE		ir iisu, Lii				1.00		23.00	46.20
M GLASS, RE						1.00	427.00		328.79
	WINDSHIEL	D GLASS				2.00		23.00	418.88
	RR WINDOW	D GLASS				3.00			4.62
	STRIP, TRUN	IK I ID						23.00	20.79
M PANEL, TR		IK LID				1.00	157.00 795.00		120.89
	RUNK LID,L	н				1.00	203.00		612.15
	RUNK LID,R					1.00	203.00		156.31 156.31
M LATCH, TR						1.00	218.00		167.86
	TRUNK LID	LATCH				1.00		23.00	15.40
	RR END PA					1.00	336.00		258.72
M MARK, THE						1.00		23.00	53.90
M MARK, ATT						1.00		23.00	16.17
	RUNK ROOM	FLOOR				1.00	195.00		150.15
M TRIM, RR						1.00		23.00	50.82
	D BODYKIT	S				1.00	1643.00		1314.40
Confirm &	aganted b								
CONTINUA (accepted b	у			7	% GST on	Ne:		13,274.2 929.1
						To	tal Payab	le	14,203.4
Authorized	signatory	and company	stamp						

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.