



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21003553/TUtd3e2	
			Date: 24/05/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMY 8896T	Veh. Inspected	SMW 3623H
	Policy No.	D21MTPV01002575	Coverage (\$)	0.00
	Claim No.	CMTD2100846/LOR	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	18/03/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FREED	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	GB53105095	Colour	BLACK
	Odometer	8721 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/65 R15	DUNLOP	6 mm
	L/H Front Tyre	185/65 R15	DUNLOP	6 mm
	R/H Rear Tyre	185/65 R15	DUNLOP	6 mm
	L/H Rear Tyre	185/65 R15	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/03/2021	Inspection Date	23/03/2021
	Survey held at	FEI AUTO 25 KAKI BUKIT ROAD 4, #03-33, SYNERGY @ KB, SINGAPORE 417800		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	