

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: WAN.512884.H Date: 29th March 2021

Our Ref: CS1/LAW21003564/Avd3e2

M/s Riaz LLC

133 New Bridge Road #09-09 Chinatown Point Singapore 059413

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKZ 49T

INSURED VEHICLE: SHA 3203L ACCIDENT DATE: 23/08/2018

We thank you for your instruction on 22/02/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKZ 49T from M/s Premier Appraiser Services.
- b) Final Repair Bill of SKZ 49T from M/s Precise Auto Service.
- c) Singapore Accident Statement of Vehicles SKZ 49T and SHA 3203L
- d) Colour damaged vehicle photographs of SKZ 49T.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SKZ 49T

Make & Model : Mercedes Benz S350 CGIL Chassis Number : WDD2211572A408046

Year of Registration : 2011
Engine Capacity : 3498 cc

- 2. We recommend that the repairs of the entire damage require about <u>4 (Four)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.