

then recite

Not Authorized
4/5 to 6800/ 5 days.

SCV34B

Make & Model:

MERCEDES C180

Chassis No:

WDD2040452A623359

	Parts/Labour	QTY	Unit Price	Price	Recommend
	Rear Bootlid	1pc		1455.00	22/Sept ✓
2	Rear Bootlid Spoiler	1pc		600.00	R X
3	Rear Bootlid Emblem logo	1pc		65.00	All ✓
4	Rear Bootlid Hander Moulding	1pc		265.00	Sur X
5	Rear Bootlid Lock	1pc		385.00	Sur/Em ✓
6	Rear Licence Plate with Casing	1pc		50.00	Sur X
7	Taillamp (Left & Right)	2	@542	1084.00	One ✓
8	Rear Bumper	1pc		1345.10	Dis ✓
9	Rear Bumper Tow Cover			45.00	X
10	Rear Bumper Clips	1set		50.00	All ✓
11	Rear Bumper Lower Garnish	1pc		395.10	Refined ✓
12	Rear Bumper Reverse Sencer	1set		250.00	shaded ✓
13	Exhuast Pipe	1pc		1100.00	11 X
14	Rear Reinforcement	1pc		615.00	Surf ✓
15	Rear End Panel	1pc		820.01	9.6gms ✓
16	Rear End Panel Garnish	1pc		168.00	Two ✓
17	Whether Stripe	1pc		261.00	Two ✓
18	Spare Tyre Cupboard	1pc		366.00	waged ✓
19	Rear Fender Garnish (Left & Right)	2	@342	684.00	11 X
20	Rear Fender Garnish Clips (Left & Right)	1set		30.00	11 X
				(10%)	

Labour				
	check Wiring		\$ 100.00	30
	Anti Rust Proofing		\$ 100.00	60
3	Remove & Refix Rear Exhaust Pipe		\$ 100.00	12X
4	Panel Beating		\$ 1,000.00	800
5	To Putty & Spray Painting Paint Work (Pearl White)		\$1,200.00	1080
6				

STYTECH AUTO PTE. LTD.
 2 Kaki Bukit Ave 2 #02-30
 Kaki Bukit Autohub Singapore 41792
 Tel: 6444 8125 Fax: 6445 3310
 GST Reg. No.: 201601539K
 Co. Reg. No.: 201601539K

Email: stytechent@singnet.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

9-7259.21
 100%
 7-6533.28
 L- 1970.00
 8503.28
 6802