

REPAIR DETAILS**Reference**

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2021)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	ComfortDelGro Engineering Pte Ltd/SHC8400R/22/03/2021 13:30	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*1,106.00 FL <i>de</i>
2	1		*REAR BUMPER UNDER COVER	20.00	0.00	*228.00 FL <i>an</i>
3	1		*REAR BUMPER REINFORCMENT	20.00	0.00	*428.40 FL <i>Run</i>
4	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL <i>ice</i>
5	1		*REVERSE SENSOR	0.00	0.00	*135.70 FX <i>un</i>
6	2		*REAR FENDER ADVERTISEMENT STICKER RH/LH	0.00	0.00	*200.00 F <i>ng</i>
7	1		*REAR BUMPER ADVERTISEMENT STICKER	0.00	0.00	*50.00 F <i>ant</i>
8	1		*EXHAUST MUFFLER LH	20.00	0.00	*967.70 FL <i>Ant</i>

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) 3,137.80
 - List Item Discount on L Items (S\$) 550.42

Total Parts (S\$) 2,587.38

ComfortDelGro Engineering Pte Ltd/SHC8400R/22/03/2021 13:30. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

1356
 20% = 1084.80
 SN. 250.

Lim Tien Siong

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	280 300.00
2	SPRAY PAINTING	New	250 300.00
3	R/I EXHAUST SYSTEM	New	120 120.00
4	R/I REVERSE SENSOR	New	30 120.00
Gross Labour Cost (S\$)			840.00

ComfortDelGro Engineering Pte Ltd/SHC8400R/22/03/2021 13:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tax Fee \$60.00 nett ✓

620-

1965.80

4/5 \$1500

02 days \$

Tanphir 17795747

wp' 23/3/21 @ 12pm

4/5 Resurvey after repair

Tanphir e/kh and w...

02 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: