

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : **SMY 6420 X**

Model : Mercedes GLB 200

Year :

Chassis No :

After-Paint:

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Tailgate	1	\$ 2,986.39	\$ 2,986.39
2	Tailgate logo	1	\$ 110.00	\$ 92.00 110.00
3	Tailgate emblem 'GLB 200'	1	\$ 198.00	\$ 120.00 198.00
4	Tailgate inner lock	1	\$ 384.60	\$ 384.60
5	Tailgate inner lock sticker	1	\$ 88.00	\$ 88.00
6	Tailgate weatherstrip	1	\$ 498.00	\$ 498.00
7	Tailgate windscreen moulding	1	\$ 314.55	\$ 314.55
8	Rear bumper	1	\$ 1,858.00	\$ 1,350.00 1,858.00
9	Rear bumper lower	1	\$ 983.35	\$ 775.00 983.35
10	Rear bumper chrome difusser	1	\$ 788.65	\$ 729.14 788.65
11	Rear bumper inner sponge	1	\$ 325.60	\$ 325.60
12	Rear bumper reinforcement	1	\$ 851.33	\$ 795.00 851.33
13	Rear bumper reinforcement bracket	2	\$ 152.00	\$ 304.00
14	Rear bumper side retainer	2	\$ 75.00 105.60	\$ 150.00 371.20
15	Rear bumper outer chrome garnish	1	\$ 441.60	\$ 190.00 441.60
16	Rear bumper bracket	2	\$ 145.82	\$ 291.64
17	Rear bumper arch garnish	2	\$ 399.75	\$ 799.50
18	Rear bumper reflector	2	\$ 98.00	\$ 65.00 196.00
19	Rear bumper centre beam	1	\$ 383.00	\$ 230.00 383.00
20	Rear bumper lower centre cover	1	\$ 428.79	\$ 305.00 428.79
21	Rear bumper tow cover	1	\$ 185.00	\$ 50.00 185.00
22	Rear bumper reverse sensor	2	\$ 190.00 245.80	\$ 380.00 983.20
23	Rear end panel	1	\$ 2,136.60	\$ 1,840.00 2,136.60
24	Rear end panel top garnish	1	\$ 425.75	\$ 425.75
25	Taillamp	2	\$ 1,098.00	\$ 2,196.00
26	Taillamp lower bracket	2	\$ 198.00	\$ 396.00
27	Rear exhaust pipe	1	\$ 3,600.00	\$ 3,600.00
28	Rear exhaust pipe heatshield	2	\$ 336.00	\$ 672.00
29	Rear exhaust pipe chrome cover	2	\$ 358.00	\$ 716.00
30	Front headrest	2	\$ 1,440.00	\$ 2,880.00
31	Airbag control module	1	\$ 1,899.00	\$ 1,899.00
			Parts Sub Total :	\$ 70 28,691.75
			10% Discount	\$ 2,869.18
			PARTS TOTAL :	\$ 25,822.58

2021
GTRX
NECV
NDX
BRV
BRV
BRV
NNX
DDV
NNX
NECV
BRV
NSX
NDX
BRV
BRV
BRV
DLV
SCV
DDV
NDX
NDX
NNX
NDX
NDX
RX

RH 1

2

Reset

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Tailgate sealant	1	\$ 100.00	\$ 100.00
3	Tailgate windscreen sealant	1	\$ 100.00	\$ 100.00
4	Tailgate windscreen inner seal	1	\$ 80.00	\$ 80.00
5	Tailgate windscreen primer & cleaner	1	\$ 60.00	\$ 60.00
6	Tailgate inner trim board clips	1	\$ 60.00	\$ 60.00
7	Rear bumper clips	1	\$ 60.00	\$ 30.00 60.00
8	Rear bumper lower clips	1	\$ 60.00	\$ 30.00 60.00
9	Rear bumper chrome difusser clips	1	\$ 60.00	\$ 30.00 60.00
10	Rear bumper outer chrome garnish clips	1	\$ 60.00	\$ 30.00 60.00
11	Rear bumper arch garnish clips	1	\$ 60.00	\$ 30.00 60.00
12	Rear bumper lower centre cover clips	1	\$ 60.00	\$ 30.00 60.00
13	Rear bumper reverse sensor seal	2	\$ 12.00 60.00	\$ 24.00 272.00
14	Rear end panel sealant	1	\$ 100.00	\$ 100.00
15	Rear end panel top garnish clips	1	\$ 60.00	\$ 60.00
16	Taillamp seal	2	\$ 60.00	\$ 120.00
17	Taillamp clips	2	\$ 60.00	\$ 120.00
SPECIAL NETT TOTAL :				\$ 324.00 1,512.00

Nos.	LABOUR	S\$
1	R&R tailgate component	\$ 150.00
2	R&R tailgate windscreen	\$ 250.00
3	R&R rear bumper reverse sensor	\$ 60.00 100.00
4	R&R rear exhaust pipe	\$ 150.00
5	R&R front seat headrest	\$ 300.00
6	Upholstery	\$ 300.00
7	Check wiring	\$ 50.00 100.00
8	Diagnostic reset fault code	\$ 120.00 300.00
9	Coating	\$ 630.00
10	Panel beating	\$ 1000.00 1,800.00
11	Rust proofing	\$ 200.00
12	Spray painting	\$ 600.00 1,800.00
LABOUR TOTAL :		\$ 1830.00 6,080.00

Survey
22/3/2021
Tatim
lin

Resurvey
24/3/2021
Tatim
lin

Lump sum repair
Repair days 7

PARTS TOTAL : \$ 25,822.58
SPECIAL NETT TOTAL : \$ 1,512.00
LABOUR TOTAL : \$ 6,080.00
GRAND TOTAL : \$ 33,414.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PARTS 6,364.03
S/N 324.00
LABOUR 1830.00
8518.03
@ 20% 1703.61
6,814.42

HS 6,800/2
Tatim lin 2/4/2021