



Vfix Auto Pte Ltd
26 Chia Ping Road
Singapore 619977
Email: contact@vfixauto.com.sg
Tel: 64552957 Fax: 68628669
UEN / GST REG No.: 201830761R

ESTIMATE

DATE : 24/3/2021
ACC DATE : 18/3/2021
POLICY NO :
SHEET NO. 1 OF 1 SHEET

Attention: Motor Claim Department

RE : VEHICLE NO : XD6344M Isuzu (Lonpac)

S/NO.	QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	1	Front Cabin Head Assembly		60,000.00

30,000/-

S/NO.	QTY	LABOUR & MISCELLANEOUS :	AMOUNT S\$
1	1	To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front door pillar, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments	-
2	1	To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	-

\$ -

GRAND TOTAL : \$ 60,000.00

ISSUED BY

VERIFIED BY

ESTIMATE CONFIRMED AND ACCEPTED BY

Koh Weng Sheng

KOH WENG SHENG

KEN TAN

NAME, SIGNATURE, DATE SIGNED

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: