

# Assessment Details

- General & Workshop Details
  - Vehicle & Driver Details
  - Vehicle Condition
  - Taxes & Ratio
  - Parts & Labour
  - Miscellaneous
- Summary

## General Details

Involving	TPVD MERCEDES S300L (SFF2345P)
Date of Loss	19 March 2021
Time of Loss	14:55
Loss Description	SFZ1008P > SHC7450C (INSD) > SFF2345P (TP)
Comment	<input type="text"/>

## Workshop Details

Total Rebate Amount	<input type="text" value="0"/>
Nett Loss Amount	-\$32,714.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>

# Assessment Details

- General & Workshop Details
  - Vehicle & Driver Details**
  - Vehicle Condition
  - Taxes & Ratio
  - Parts & Labour
  - Miscellaneous
- Summary

## Vehicle & Driver Details

Vehicle Registration#	SFF2345P	Purchase Date	<input type="text" value="DD/MM/YYYY"/>
Registration State	<input type="text" value="SINGAPORE"/>	Registration Date *	<input type="text" value="24/09/2007"/>
Mileage	<input type="text" value="106913"/>	Age of Vehicle	13

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<input type="text" value="2007"/>

### Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	HO CHING PENG	<input type="text"/>

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD MERCEDES	MERCEDES BENZ
Model	S300L	S300L
Type		
Type of Paint		
Chassis No		WDD2211542A147020
Engine No		27294630648716
Engine Capacity		2997
Sum Insured		0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth		DD/MM/YYYY 
Age	0	
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	0	
Driver License #		
License Type		
License Issue Date		DD/MM/YYYY 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		DD/MM/YYYY 
Address	Singapore	
Address type	Personal Correspondence	
Gender	Unknown	
Marital status	Unknown	
Identification #	TBC	

# Assessment Details

General & Workshop Details Vehicle & Driver Details **Vehicle Condition** Taxes & Ratio Parts & Labour Miscellaneous

Summary

## Detailed Assessment

Inspection Date \*

23/03/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver Excess

0

## Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake  
(Serviceable)

Yes

No

Handbrake  
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

### Tyre Condition

---

Age of Tyres

Front Tyre Size

235/55R17

Front left side

MICHELIN8mm

Front right side

MICHELIN8mm

Spare wheel

Rear Tyre Size

235/55R17

Rear left side

MICHELIN8mm

Rear right side

MICHELIN8mm

# Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio**
- Parts & Labour
- Miscellaneous
- Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text" value="0"/>	Salvage%	<input type="text" value="0"/>
Discount%	<input type="text" value="10"/>	Settlement%	<input type="text" value="100"/>

## Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Cash Loss	<input type="radio" value="Yes"/> Yes	<input checked="" type="radio" value="No"/> No	Part supplied by
Paint Material Ratio	<input type="text" value="80"/>				

A  
X  
A



Service Requests

Messages

Claims

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio **Parts & Labour** Miscellaneous Summary

Parts

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR BOOTLID	Repair	0	0	No	0	0	0	0	0
	0	1		REAR BOOTLID S300 EMBLEM	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BOOTLID LOGO	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BOOTLID 7G TRONIC EMBLEM	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BOOTLID INNER LOCK MECHANISM	Repair	0	0	No	0	0	0	0	0
	0	1		REAR BOOTLID CATCH	Repair	0	0	No	0	0	0	0	0
	0	1		REAR BOOTLID WEATHERSTRIP	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BOOTLID INNER TRIM	Serviceable	0	0	No	0	0	0	0	0

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR BOOTLID CHROME MOULDING	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BOOTLID SIDE GARNISH INNER RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER	Bent	0	1840	No	0	10	0	0	1656
	0	1		REAR BUMPER SIDE RETAINER LH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER SIDE RETAINER RH	Cracked	0	120	No	0	10	0	0	108
	0	1		REAR BUMPER REINFORCEMENT BEAM	Bent	0	650	No	0	10	0	0	585
	0	1		REAR BUMPER REINFORCEMENT BRACKET	Repair	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER TOW COVER	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER INNER PLASTIC BEAM	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILLAMP RH	Cracked	0	650	No	0	10	0	0	585

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		TAILLAMP BRACKET RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		TAILLAMP MOULDING RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR END PANEL	Repair	0	0	No	0	0	0	0	0
	0	1		REAR END PANEL TOP GARNISH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR EXHAUST SHIELD	Dented	0	235	No	0	10	0	0	211.5
	0	1		REAR SPARE TYRE FIBRE PANEL	Serviceable	0	0	No	0	0	0	0	0
	0	1		KEYLESS SENSOR	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER LOWER BRACKET LH	Cracked	0	90	No	0	10	0	0	81
	0	1		REAR BUMPER LOWER BRACKET RH	Cracked	0	90	No	0	10	0	0	81
	0	1		TAILLAMP SIDE GARNISH COVER RH	Damaged	0	85	No	0	10	0	0	76.5

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
------	-------	-------------------------	-----------	------------------------	------------------------	-----------------------	-----------------------	-----------------	---------	--------

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	0	250	0	0	Reviewing		
	0		SPRAY PAINTING ON ACCIDENT AREA	0	480	0	0	Reviewing		
	0		CHECK & REPAIR WIRING SYSTEM	0	20	0	0	Reviewing		
	0		R&R BOOTLID COMPARTMENT	0	0	0	0	Deny		
	0		RESET BOOTLID LOCK MECHANISM	0	0	0	0	Deny		
	0		R&R EXHAUST HEATSHIELD SYSTEM	0	30	0	0	Reviewing		
	0		RESPRAY TUFF KOTE ON AFFECTED AREA	0	0	0	0	Deny		
	0		R&R REVERSE SENSOR & RESETTING OF SYSTEM	0	0	0	0	Deny		

<< Assessment Details

Summary

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 3 DAYS	Reviewing	0	0		
	0	REAR BUMPER CLIPS	Reviewing	0	50	NECESSARY	
	0	REVERSE SENSOR WITH HOLDERS	Reviewing	0	260	SHORTED	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REVERSE SENSOR WIRE HARNESS	Reviewing	0	250	CUT	
	0	REAR END PANEL SEALANT	Deny	0	0	NOT NECESSARY	
	0	REAR SPARE TYRE PANEL SEALANT	Deny	0	0	NOT NECESSARY	
	0	REAR BOOTLID INNER TRIM CLIPS	Deny	0	0	NOT NECESSARY	

# Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

## Summary

Estimated Claim Amount \$0.00 Adjusted Claim Amount \$4,724.00

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts		
Labour		
Spare Parts		
Miscellaneous		

Submit for Review



## Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour **Miscellaneous**

### Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FINAL LUMP SUM	Reviewing	0	3750		

## Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

### Summary

Estimated Claim Amount \$0.00 Adjusted Claim Amount \$3,750.00

CATEGORY	ESTIMATE	ADJUSTED
----------	----------	----------

Miscellaneous

Submit for Review