

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0238/2021/HR
DATE : 22-Mar-21
WIP : 20253

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/3/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. LIM ENG THAI
ADDRESS : 487 YIO CHU KANG ROAD
#01-04
SINGAPORE 787059
TELEPHONE : HP +65 91998088
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800084746-01
VEHICLE NO : **SMD 44 Z**
MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC
MODEL YEAR : 17/7/2018
ENGINE NO : CVK 060749
CHASSIS NO : WAUZZZF40
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Mar-21
PLACE OF ACCIDENT : 427 TAMPINES STREET 41 CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMD 44 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,000.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 5,122.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 44 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,787.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 587.00	
3	FRONT BUMPER AIR GUIDE - LH	1	\$ 63.00	
4	FRONT BUMPER GUIDE SECTION - LH	1	\$ 36.00	
5	FRONT BUMPER LOWER CLOSING ELEMENT - CENTER	1	\$ 210.00	
6	FRONT FENDER - LH	1	\$ 767.00	
7	FRONT FENDER ATTACHMENT PARTS	1	\$ 202.00	
8	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 72.00	
9	FRONT FENDER UPPER BRACKET - LH	1	\$ 35.00	
10	FRONT FENDER BRACE - LH	1	\$ 118.00	
11	FRONT FENDER LONG LEDGE COVER - LH	1	\$ 31.00	
12	FRONT FENDER SHORT BRACE - LH	1	\$ 23.00	
13	FRONT WHEEL HOUSING LINER - LH	1	\$ 240.00	
14	WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 233.00	
15	FRONT WHEEL SPOILER - LH	1	\$ 73.00	
16	FRONT WHEEL LOWER SPOILER TRIM - LH	1	\$ 35.00	
17	STONE CHIP GUARD LH	1	\$ 51.00	
18	LED HEADLIGHT - LH	1	\$ 7,693.00	
19	LED HEADLIGHT LIFT CYLINDER - LH	1	\$ 210.00	
20	AIR GUIDE GRILLE - LH	S/N	TBC	
SUB TOTAL SPARE PARTS		:	\$ 12,466.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 44 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	SUNDRIES		\$ 250.00	
TOTAL SPARE PARTS		:	\$ 12,716.00	
TOTAL LABOUR CHARGES		:	\$ 5,122.00	
GRAND TOTAL		:	\$ 17,838.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT