



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692

GST Reg No: MX-0869103-NO Business Reg No: 394773/00D

E-mail: nphauto@pacific.net.sg



Your Ref :

Page : 1/2

Our Ref : TP0025/03/21

Date : 23/03/2021

THIRD PARTY CLAIM

M/S : SIN HAI SHIN LEE SEAFOOD PTE LTD
BLK 213 PASIR RIS STREET 21
#08-212
SINGAPORE 510213

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : GBG2218R - TOYOTA DYNA
INSURED : SIN HAI SHIN LEE SEAFOOD PTE LTD ENGINE# :
DATE OF ACCIDENT : 17/03/2021 CHASSIS# :
POLICY NO : 1800057333-02

*Not Paid
2/5 \$2400
3dys
23/3/21*

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Replacement of Parts				
1 front headlamp assy RH <i>cm</i>	1@	1145.80	1145.80	1,145.80
2 front bumper <i>To in</i>	1@	529.70	529.70	529.70
3 front bumper bracket <i>Sub</i>	1@	225.10	225.10	225.10
4 front stepboard fibre <i>cm</i>	1@	400.00	400.00	400.00
5 front door RH <i>cm</i>	1@	1600.00	1600.00	1,600.00
6 front door w/strip rubber <i>11</i>	1@	195.00	195.00	195.00
7 front side panel RH <i>cm</i>	1@	212.50	212.50	212.50
8 front bumper fog lamp grille RH <i>ms</i>	1@	70.00	70.00	70.00
				4,378.10

Total Material

Special Nett Items

8 front number plate <i>Best</i>	1@	45.00	45.00	45.00
9 front door body lettering <i>ner</i>	1@	45.00	45.00	45.00
				90.00

Total S/Nett

Labour & Misc

1 Remove & install f/door, f/headlamp, f/bumper, side panel, f/headlamp, f/bumper, knock door pillar and restraighthen body.			750.00	
2 Spray painting.			850.00	
3 Check wiring system.			25.00	
			1,625.00	
			0.00	

Total Labour

\$1,625.00

*2.2542
25.2
1906.50
3011.5*



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692

GST Reg No: MX-0869103-NO Business Reg No: 394773/00D

E-mail: nphauto@pacific.net.sg



Your Ref :

Page : 2/2

Our Ref : TP0025/03/21

Date : 23/03/2021

THIRD PARTY CLAIM

Nett Total Before Gst

\$4,998.57

Your faithfully

NPH AUTO SERVICE
(Manager)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: