

(12)



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 31721

Vehicle Insured : GBD 5282 A
Accident Date : 23-Mar-2021

Date : 23-Mar-2021

Our Ref : 021090 (CHINA) / QUEK

PAGE : 1

MI YINLONG (MR)
Singapore

Not Authorized
11 PM 8
Recovery After Paving

6 days

ESTIMATED COST OF REPAIR FOR HONDA VEZEL 1.5X CVT (2018) SLW4460R

1 pc front bumper - top		Ry 489.80	✓
1 pc front bumper - lower		CM 195.60	✓
1 pc front bumper lower centre grille		Dis 77.50	X
1 pc front bumper lower rubber		Sm 89.90	X
1 pc RH front bumper foglamp		my CM 327.00	✓
1 pc RH front bumper foglamp cover		Sm 45.00	X
2 pcs front bumper side retainer (LH/RH)	@ S\$ 17.50	dis CM 35.00	4 17.50
1 pc front bumper reinforcement		R 321.00	X
2 pcs front bumper reinforcement top moulding (LH/RH)	@ S\$ 19.60	R 39.20	X
2 pcs front bumper inner air guide	@ S\$ 36.00	Sm 72.00	X
10 pcs front bumper clips	@ S\$ 3.50	my 35.00	✓
2 pcs headlamp assy (LH/RH) <i>olsm</i>	@ \$1710.20	3,420.40	4 1710.20
2 pcs headlamp lower bracket (LH/RH)	@ S\$ 35.00	dis CM 70.00	4 35
1 pc front grille		CM 351.80	✓
2 pcs front grille side bracket (LH/RH)	@ S\$ 19.60	CM 39.20	4 19.60
1 pc front grille centre bracket		CM Sm 38.70	X
1 pc front grille outer garnish		CM 385.00	✓
1 pc front grille outer chrome		75.00	7
1 pc front grille logo		my 23.40	✓
10 pcs front grille clips	@ S\$ 3.50	my 35.00	✓
1 pc front grille top garnish		dis 85.00	✓
8 pcs front grille top garnish clips	@ S\$ 3.50	my 28.00	✓
1 pc horn		Sm 58.50	X
1 pc wiper washer tank		Sm 75.00	X
1 pc wiper washer tank motor		Sm 58.60	X
1 pc RH front fender		Ry 580.00	✓

Con't Page 2 ...



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : GBD 5282 A
Our Ref : 021090

Page : 2
No. : 31721

1 pc	RH front fender inner shield		Div	130.00	✓
8 pcs	RH front fender inner shield clips	@ S\$ 3.50	na	28.00	✓
2 pcs	front fender wheel arch garnish (LH/RH)	cl/mir @ S\$153.00	ntm	306.00	let ✓
1 pc	bonnet		R	892.30	X
2 pcs	bonnet hinges (LH/RH)	@ S\$ 48.50	n	97.00	X
1 pc	bonnet lock		n	98.50	X
1 pc	bonnet pull lock cable		sn	42.50	X
1 pc	air con condenser		pu	868.10	✓
1 pc	front support panel			411.90	7X
1 pc	RH front rim		nc	801.40	✓
1 pc	RH front shock absorber			430.10	7X
1 pc	RH front shock absorber mounting			35.00	7X
1 pc	RH front shock absorber stopper			26.90	7X
1 pc	RH front shock absorber cover			32.00	7X
1 pc	RH front knuckle arm			249.70	7X
1 pc	RH front knuckle arm bearing			135.50	7X
1 pc	RH front bearing hub			187.50	7X
1 pc	RH front lower arm			380.00	7X
1 pc	RH front stabilizer bar linkage		sn	60.00	X
1 pc	RH front tie rod			88.70	7X
1 pc	RH front tie rod end			71.80	7X

				12,423.50	
Less 20% :				-2,484.70	

				9,938.80	
1 pc	front number plate		sn	40.00	sn X
1 pc	RH front bumper foglamp wireharness (local repair)		sn	250.00	sn ✓
1 pc	RH front tyre		pu	420.00	sn X✓

Con't Page 3 ...



CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : GBD 5282 A
Our Ref : 021090

Page : 3
No. : 31721

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

750.00 *5501*

To focus headlamps. To check front
wiring and lighting operation.

50.00 *201*

To dismantle and check front under-
carriages. To replace affected
portions.

240.00 *7*

To conduct front wheel alignment
test.

100.00 *601*

To putty and respray on affected
portions.

950.00 *8001*

Total : S\$12,738.80
=====

Singapore Dollars Twelve Thousand Seven Hundred
and Thirty Eight and Cents Eighty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

6587.20
- 20%
5269.76 (c/parts)
670 (s/n item)
+ 1430 (Labour)
57369.76