

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore-568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : SEAH SOON HONG FREDDY
56 PARK VILLAS RISE
SINGAPORE 545352

Claim No: MC1901844
No: MF1901779
Date: 28 Jul 2021
Policy No: P2286695
Veh Reg No: SBZ2969G
Make/Model: SKODA KODIAQ 2.0 TSI 4X4
Chassis No: TMBMD9NS6K8061068
TP Ins Co: AIG

ATTN:

Your Ref No: SBZ2969G
Claim Type: Third Party
Accident Date: 23/03/2021
TP Veh Reg No: GBK7352G

DRAFT FINALISATION

Amended Repair Cost to Vehicle No (For Finalization):SBZ2969G

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 FRONT DOOR LH	1 PC	2,875.00	
2 FRONT DOOR PROTECTOR LH	1 PC	372.00	
3 FRONT DOOR RUBBER (AT DOOR) LH	1 PC	186.00	
4 SIDE MIRROR COVER LOWER W MOTOR ARM LH	1 PC	891.25	
		4,324.25	
	Less 10%	432.43	3,891.83
Special Nett			
5 SOUND PROOFING, CERAMIC/GLASS COATING AND SIDE MIRROR WRAP ✓ NEC	1 PC	970.00 ✓	
6 SIDE MIRROR COVER LH	1 PC	197.95	
		1,167.95	1,167.95
LABOUR			
7 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
8 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	60.00	
9 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR FRONT INNER PANELS INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	200.00	
10 TO SPRAY FRONT DOOR LH,SIDE MIRROR COVER LH.	1 PC	250.00	
		530.00	530.00
		Total	S\$ 5,589.78
		Add GST @ 7%	391.28
		Total Amount Payable	S\$ 5,981.06

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED EIGHTY ONE AND CENTS SIX ONLY

The above vehicle was surveyed by GUO QIANG - LKK on 31/03/2021

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint Singapore-568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE