

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Alfred Toh

Date: 22 Apr 2021

Preliminary Advice

Insured Vehicle No	: GBB4130Y	Accident Date	: 23/03/2021
TP Vehicle No	: SMN4677T	Assignment Date	: 25/03/2021
Make	: HONDA CIVIC	Est. Duration of Repair	: 4
Date of Inspection	: 25/03/2021		
Inspection At	: EURO SUCCESS SERVICES PTE LTD (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,311.68
Revised Amount	:S\$	4,412.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,412.80
Lump Sum Repair	:S\$	3,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :