

Date: 20.03.2021
Vehicle No: SMM4227P
Model: PORSCHE BOXSTER S 3.4A
Chassis: WPOZZZ98ZDS121588-2012
Reg.Year: 2012

Third Party Insurer: AIG
Third Party Veh No: SMM6701Z
Date of Accident: 19.03.2021

Not Authaird
3 days 11 Pay & Recovery After Paint

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1	<i>Buc/Net</i>	\$2,580.80 ✓
2	REAR BUMPER LOWER DIFFUSER CENTER	1		\$282.50 7
3	REAR BUMPER LOWER RETAINER FRAME	1		\$480.25 7
4	REAR BUMPER PARKING SENSOR	2	\$323.75 <i>sm</i>	\$647.50 X
5	REAR BUMPER INNER BRACKET LH	1		\$283.40 7
6	REAR BUMPER INNER BRACKET RH	1		\$283.40 7
7	REAR BUMPER REINFORCEMENT	1		\$852.50 7
SUB TOTAL				\$5,410.35
LESS 10%				-\$541.04
PARTS TOTAL				\$4,869.32

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>Net</i> \$150.00 ✓
2	REAR BUMPER GROMMET	1		\$200.00 7
3	REAR NUMBER PLATE	1		<i>Net</i> \$50.00 } 455m
4	REAR NUMBER PLATE HOLDER	1		\$50.00
S/N TOTAL				\$450.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC. \$500.00 *300*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER & ETC. \$400.00 *320*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC. \$120.00 *60*

TO DIAGNOSIS FAULT CODE & RESET MEMORY. \$150.00 7

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$120.00 *30*

LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during repair - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		LABOUR TOTAL	\$1,290.00
TingAn		TOTAL	\$6,609.32

Head office
6 Kung Chong Road Singapore 150143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch
9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 0010 | Fax: (+65) 6481 1003

Branch (Motor Insurance Claims)
Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

Date:

OW™