

Date: 20.03.2021
Vehicle No: SMM4227P
Model: PORSCHE BOXSTER S 3.4A
Chassis: WP0ZZZ98ZDS121588-2012
Reg.Year: 2012

Third Party Insurer: AIG
Third Party Veh No: SMM6701Z
Date of Accident: 19.03.2021

*Not Authorised
3 day, 11 Pm @ 3700hr
Resurvey After Paint*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER <i>2499</i>	1		
2	REAR BUMPER LOWER DIFFUSER CENTER	1	<i>Buc 100</i>	\$2,580.80
3	REAR BUMPER LOWER RETAINER FRAME	1		<i>CM</i> \$282.50
4	REAR BUMPER PARKING SENSOR <i>0295</i>	1		<i>Sn</i> \$480.25
5	REAR BUMPER INNER BRACKET LH	2	<i>Mon</i> \$323.75	<i>Fee</i> \$647.50
6	REAR BUMPER INNER BRACKET RH	1		<i>R</i> \$283.40
7	REAR BUMPER REINFORCEMENT <i>789</i>	1		<i>R</i> \$283.40
		1		<i>By</i> \$852.50
SUB TOTAL				\$5,410.35
LESS 10%				-\$541.04
PARTS TOTAL				\$4,869.32

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>Re</i> \$150.00
2	REAR BUMPER GROMMET	1		<i>Sn</i> \$200.00
3	REAR NUMBER PLATE	1		<i>Re</i> \$50.00
4	REAR NUMBER PLATE HOLDER	1		\$50.00
S/N TOTAL				\$450.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC.

\$500.00 *3000*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER & ETC.

\$400.00 *3200*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$120.00 *600*

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

non \$150.00 *X*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$120.00 *300*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) of
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LABOUR TOTAL \$1,290.00

TOTAL \$6,609.32

TingAn

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)
Bik 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

