

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722
Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautopl@gmail.com

SJE :

Vehicle Nos: SKH 4618 U

Date of Survey :

Made : Toyota

Date of ReSurvey:

Model : Vios

Contacts :

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear bumper	1	\$ 547.60	\$ 547.60
2	Rear bumper reflector RH 1	2	\$ 259.30	\$ 518.60
3	Rear bumper side retainer front	2	\$ 153.80	\$ 307.60
4	Rear bumper side retainer rear	2	\$ 189.20	\$ 378.40
5	Rear fender RH 18, 19	1	\$ 785.40	\$ 785.40
6	Rear fender inner trim board RH	1	\$ 489.60	\$ 489.60
7	Rear fender inner cowling RH	1	\$ 147.80	\$ 147.80
8	Rear air vents	1	\$ 86.30	\$ 86.30
9	Rear windscreen moulding	1	\$ 185.30	\$ 185.30
10	Rear end panel	1	\$ 588.30	\$ 588.30
11	Rear end panel top garnish	1	\$ 198.50	\$ 198.50
12	Taillamp RH	1	\$ 652.80	\$ 652.80
13	Rear exhaust	1	\$ 549.30	\$ 549.30
14	Rear exhaust head shield	1	\$ 144.00	\$ 144.00
15	Rear exhaust mounting	2	\$ 65.80	\$ 131.60
16	Bonnet	1	\$ 682.30	\$ 682.30
17	Bonnet hinge	2	\$ 54.20	\$ 108.40
18	Bonnet inner lock	1	\$ 84.30	\$ 84.30
19	Bonnet inner lock cable	1	\$ 110.00	\$ 110.00
20	Front grille	1	\$ 320.50	\$ 320.50
21	Front grille logo (bumper)	1	\$ 85.60	\$ 85.60
22	Front grille outer chrome	1	\$ 85.90	\$ 85.90
23	Front bumper	1	\$ 658.20	\$ 658.20
24	Front bumper bracket	2	\$ 187.30	\$ 374.60
25	Front bumper centre inner garnish	1	\$ 336.50	\$ 336.50
26	Front bumper inner pad	1	\$ 314.50	\$ 314.50
27	Front bumper side retainer	2	\$ 84.00	\$ 168.00
28	Front bumper centre grille	1	\$ 210.00	\$ 210.00
29	Front bumper fog lamp	2	\$ 231.70	\$ 463.40
30	Front bumper fog lamp garnish	2	\$ 145.80	\$ 291.60
31	Front bumper reinforcement	1	\$ 488.60	\$ 488.60
32	Front bumper tow cover	1	\$ 58.30	\$ 58.30
33	Front support panel	1	\$ 652.00	\$ 652.00
34	Front chassis frame RH	1	\$ 687.00	\$ 687.00
35	Headlamp	2	\$ 758.20	\$ 1,516.40

BRV
BRV
NECV
NECV
CUTX R
NDX
Z HH
NSX
Z HH
Z HH
?
NDX
BTU
BTU
?
Z HH
BRV
NECV
NECV
BRV
NSX
Z HH
?
NECV
BRV
? 0/5 HH
? 0/5 HH
?
MISV
Z HH
Z HH
?

Nos.	SPECIAL NETT	Qty	Unit \$S	TOTAL \$S
1	Sundries	1	\$ 80.00	\$ 80.00
2	Rear bumper clips	1	\$ 30.00	\$ 30.00
3	Rear bumper reverse sensor	2	\$ 250.00	\$ 500.00
4	Rear fender sealant	1	\$ 100.00	\$ 100.00
5	Rear fender inner trim board clips	1	\$ 50.00	\$ 50.00
6	Rear fender inner cowling clips	1	\$ 50.00	\$ 50.00
7	Rear windshield sealant	1	\$ 100.00	\$ 100.00
8	Rear windshield inner seal	1	\$ 80.00	\$ 80.00
9	Rear windshield primer & cleaner	1	\$ 60.00	\$ 60.00
10	Rear end panel sealant	1	\$ 100.00	\$ 100.00
11	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00
12	Tail lamp clips	1	\$ 50.00	\$ 50.00
13	Tail lamp seal	1	\$ 60.00	\$ 60.00
14	Bonnet sealant	1	\$ 100.00	\$ 100.00
15	Front grille clips	1	\$ 50.00	\$ 50.00
16	Front bumper clips	1	\$ 50.00	\$ 50.00
17	Front bumper fog lamp garnish clips	2	\$ 50.00	\$ 100.00
18	Front support panel sealant	1	\$ 100.00	\$ 100.00
19	Front chassis frame sealant	1	\$ 100.00	\$ 100.00
20	Front fender sealant	2	\$ 100.00	\$ 200.00
21	Front fender inner cowling clips	2	\$ 50.00	\$ 100.00
22	Front door sealant	2	\$ 100.00	\$ 200.00
23	Front number plate w/ casing	1	\$ 80.00	\$ 80.00
24	Radiator coolant	1	\$ 80.00	\$ 80.00
25	Aircon fluid	1	\$ 80.00	\$ 80.00
26	Horn	1	\$ 60.00	\$ 60.00

SPECIAL NETT TOTAL : \$ 2,630.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PARTS TOTAL : \$ 24,699.19
SPECIAL NETT TOTAL : \$ 2,630.00
LABOUR TOTAL : \$ 10,730.00
GRAND TOTAL : \$ 38,059.19

Nos.	LABOUR	SS
1	R&R reverse sensor	\$ 60.00 100.00
2	R&R rear windscreen	\$ 250.00
3	R&R rear exhaust	\$ 150.00
4	R&R rear under carriage	\$ 250.00
5	R&R rear tyre and balancing	\$ 100.00
6	Rear check wiring	\$ 30.00 100.00
7	Rear upholstery	\$ 100.00 100.00
8	Rear panel beating	\$ 200.00
9	Rear rust proofing	\$ 300.00
10	Rear spray painting	\$ 300.00
11	R&R bonnet component	\$ 80.00 150.00
12	R&R air con condenser	\$ 120.00 150.00
13	R&R radiator	\$ 150.00
14	R&R radiator fan assy	\$ 80.00 150.00
15	R&R aircon compressor	\$ 150.00
16	R&R alternator assy	\$ 150.00
17	R&R starter motor assy	\$ 450.00
18	R&R engine mounting & gear box mounting	\$ 250.00
19	R&R front under carriage	\$ 100.00
20	R&R front tyre and balancing	\$ 60.00 100.00
21	Wheel alignment	\$ 300.00
22	Mount work bench	\$ 300.00
23	Chassis alignment	\$ 30.00 100.00
24	Front upholstery	\$ 100.00
25	Front check wiring	\$ 120.00 200.00
26	Front Panel beating	\$ 80.00 200.00
27	Front Rust proofing	\$ 100.00
28	Front Spray painting	\$ 10.730.00

LABOUR TOTAL :

\$ 10,730.00

PARTS TOTAL : \$ 24,699.19

SPECIAL NETT TOTAL : \$ 2,630.00

LABOUR TOTAL : \$ 10,730.00

GRAND TOTAL : \$ 38,059.19