



CAR CITY AUTO CENTRE PTE LTD

Car City Always

TO : CAAIG0001

AIG Asia Pacific Insurance Pte Ltd
NO 78 SHENTON WAY
#08-16 AIG BUILDING
SINGAPORE 079120
TEL : 64193000 FAX :
PH :
ATTN :

ESTIMATE BILL

GST Registration : 200719980C

Number : EB00000303

Date : 26/03/2021

Case No : AD00000791

Vechicle No : SJD2059D

Mileage :

Term: M.J. Lancer 2.0L

Model :

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT	
1	REAR BUMPER REINFORCEMENT <i>X BT</i>	1.0	479.00	10.00	431.10	225
2	REAR BUMPER REINFORCEMENT BRACKET RH & LH <i>X NV</i>	2.0	145.20	10.00	261.36	X
3	REAR BUMPER BRACKET <i>X NV</i>	2.0	68.40	10.00	123.12	X
4	REAR BUMPER RETAINER LH & RH <i>BT CMA</i>	2.0	74.60	10.00	134.28	97
5	REAR BUMPER REFLECTOR RH & LH <i>X NV RH X NV</i>	2.0	118.20	10.00	212.76	45
6	REAR BUMPER TOW GARNISH <i>X NV</i>	1.0	43.50	10.00	39.15	X
7	REAR BUMPER NUMBER PLATE LAMP <i>X NV</i>	2.0	55.40	10.00	99.72	X
8	REAR BOOTLID <i>BMC</i>	1.0	993.50	10.00	894.15	725
9	REAR BOOTLID HIGNES RH & LH <i>BT</i>	2.0	48.20	10.00	86.76	96.4
10	REAR BOOTLID DAMPER RH & LH <i>X NV</i>	2.0	175.60	10.00	316.08	X
11	REAR BOOTLID WEATHER STRIP <i>Twis</i>	1.0	310.20	10.00	279.18	161
12	REAR BOOTLID INNER LOCK <i>Ins</i>	1.0	368.20	10.00	331.38	145
13	REAR BOOTLID CENTRE BRAKE LAMP (LED) <i>CMA</i>	1.0	320.60	10.00	288.54	320.6
14	REAR BOOTLID LOGO	1.0	98.50	10.00	88.65	48
15	REAR BOOTLID EMBLEM (LANCER EX) <i>MC</i>	1.0	78.40	10.00	70.56	45
16	REAR BOOTLID EMBLEM (MIVEC)	1.0	98.50	10.00	88.65	48
17	REAR BOOTLID EMBLEM (MIVEC -SMALL)	1.0	78.20	10.00	70.38	30
18	REAR BOOTLID LAMPS RH & LH <i>CMA NV</i>	2.0	584.10	10.00	1,051.38	168
19	REAR BOOTLID INNER TRIM GARNISH <i>CMA NV</i>	1.0	295.70	10.00	266.13	168
20	REAR TAILLAMP RH & LH <i>CMA NV</i>	2.0	725.60	10.00	1,306.08	804
21	REAR TAILLAMP PANEL RH & LH <i>X repair</i>	2.0	296.00	10.00	532.80	X
22	REAR FENDER RH & LH <i>X repair</i>	2.0	1,200.00	10.00	2,160.00	755
23	REAR FENDER INNER TRIM GARNISH RH & LH <i>X NV</i>	2.0	425.70	10.00	766.26	404
24	REAR FENDER INNER SHIELD RH & LH <i>X NV</i>	2.0	195.40	10.00	351.72	X
25	REAR END PANEL <i>BT photo</i>	1.0	722.80	10.00	650.52	407
26	REAR END PANEL TOP GARNISH <i>ee</i>	1.0	256.70	10.00	231.03	135
27	REAR EXHAUST PIPE <i>X NV</i>	1.0	925.60	10.00	833.04	X
28	REAR EXHAUST PIPE MOUNTING <i>X NV</i>	3.0	75.50	10.00	203.85	X

E. & O. E.

CAR CITY AUTO CENTRE PTE LTD



Page 1 / 3

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

Page 1 of 3

* N = Item not subjected to GST

Issued by : Ho

Service Centre
Blk 9006 Tampines Street 93
#01-198 Singapore 528840
Tel: 6781 0300 Fax: 6782 0300
24 Hrs Helpline: 9621 4666
Email: ccacpl@singnet.com.sg



CAR CITY AUTO CENTRE PTE LTD

Car City Always

TO : CAAIG0001

AIG Asia Pacific Insurance Pte Ltd
NO 78 SHENTON WAY
#08-16 AIG BUILDING
SINGAPORE 079120
TEL : 64193000 FAX :
PH :
ATTN :

ESTIMATE BILL

GST Registration : 200719980C

Number : EB00000303

Date : 26/03/2021

Case No : AD00000791

Vehicle No : SJD2059D

4995

Mileage :

Term:

-10%: 4495.5

Model :

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT	
29	REAR EXHAUST PIPE HEAT SHIELD X NV	1.0	255.40	10.00	229.86	X
30	REAR SPARE TYRE PANEL TOP BOARD / CMA	1.0	295.80	10.00	266.22	168
31	REAR SPARE TYRE PANEL X Repair	1.0	986.70	10.00	888.03	X
32	REAR WINDSCREEN GLASS MOULDING X NV	1.0	245.00	10.00	220.50	X
List Price - Parts Sub Total					13,773.24	
33	REAR FENDER INNER TRIM GARNISH CLIPS(2 SETS) / MC	1.0	90.00	0.00	90.00	40
34	REAR FENDER INNER SHIELD CIPS (2 SETS) X NV	1.0	110.00	0.00	110.00	X
35	REAR END PANEL TOP GARNISH CLIPS / NEC	1.0	35.00	0.00	35.00	20
36	REAR BOOTLID INNER TRIM CLIPS / NEC DIS	1.0	45.00	0.00	45.00	20
37	REAR BUMPER (AFTER MARKET - ACCESSORIES)	1.0	1,800.00	0.00	1,800.00	800
38	REAR BOOTLID STICKER (RAILLIART) / NEC NEC	1.0	110.00	0.00	110.00	30
39	REAR BOOTLID EMBLEM (EVOLUTION RALLIART) / NEC	1.0	168.40	0.00	168.40	40
40	REAR BOOTLID EMBLEM (C & C) / NEC	1.0	55.00	0.00	55.00	30
41	REAR BOOTLID CENTRE BRAKE LENS(ACCESSORIES -LANCER EX) / NEC	1.0	145.00	0.00	145.00	20
42	REAR EXHAUST PIPE CHROME MUFFLER X NV	1.0	125.00	0.00	125.00	X
43	REAR NUMBER PLATE W/GARNISH / BT	1.0	55.00	0.00	55.00	40
44	REVERSE SENSORS / DM	1.0	250.00	0.00	250.00	200
45	REAR BOOTLID DUCKTAIL / DIS	1.0	600.00	0.00	600.00	500
46	REAR BOOTLID SEALANT X NV	1.0	100.00	0.00	100.00	X
47	REAR BOOTLID TRIANGEL EMBLEM / MCL	1.0	200.00	0.00	200.00	20
48	REAR WINDSCREEN SEALANT X NV	1.0	40.00	0.00	40.00	X
49	REAR SPARE TYRE PANEL RUBBER INSULATOR X NV	1.0	400.00	0.00	400.00	X
Special Nett Price - Parts Sub Total					4,328.40	1760
Parts Total					18,101.64	
50	TO REMOVE, REPLACE, REALIGN & INSTALL AFFECTED REAR DAMAGED AREAS	1.0	1,400.00	0.00	1,400.00	1000

E. & O. E.

CAR CITY AUTO CENTRE PTE LTD

Page 2/3

CUSTOMER SIGNATURE


AUTHORISED SIGNATURE

Page 2 of 3

* N = Item not subjected to GST

Issued by : Ho

Service Centre
Blk 9006 Tampines Street 93
#01-198 Singapore 528840
Tel: 6781 0300 Fax: 6782 0300
24 Hrs Helpline: 9621 4666
Email: ccacpl@singnet.com.sg



CAR CITY AUTO CENTRE PTE LTD

Car City Always

TO : CAAIG0001

AIG Asia Pacific Insurance Pte Ltd
NO 78 SHENTON WAY
#08-16 AIG BUILDING
SINGAPORE 079120
TEL : 64193000 FAX :
PH :
ATTN :

ESTIMATE BILL

GST Registration : 200719980C

Number : EB00000303

Date : 26/03/2021

Case No : AD00000791

Vehicle No : SJD2059D

Mileage :

Term:

Model :

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
51	To putty, prep & respray on affected rear damaged ares..rear bootlid, rear end panel,	1.0	1,400.00	0.00	1,400.00
52	To remove & transfer rear bootlid components to facilitate repairs	1.0	200.00	0.00	200.00
53	To remove rear interior components to facilitate repairs	1.0	200.00	0.00	200.00
54	To remove & install & align rear exhaust pipe	1.0	150.00	0.00	150.00
55	To conduct & check on all affected electrical wiring	1.0	150.00	0.00	150.00
56	To reposition, align & install reverse sensors	1.0	150.00	0.00	150.00
57	To conduct rera water seepage test	1.0	150.00	0.00	150.00
58	To provide rust coatings on affected areas	1.0	200.00	0.00	200.00
59	to reset & calibrate ECU diagnostice	1.0	250.00	0.00	250.00
60	To remove/refix rear windscreen glass	1.0	150.00	0.00	150.00
61	Towing from accident site to workshop	1.0	50.00	0.00	50.00
Labour 1 Sub Total					4,450.00
					-20%:
					7000
SINGAPORE DOLLARS : TWENTY-FOUR THOUSAND ONE HUNDRED THIRTY AND CENTS TWENTY-FIVE ONLY					
SUBTOTAL					22,551.64
GST 7.00%					1,578.61
TOTAL					24,130.25

6-7 Days -
Imp Gun repair
After repair photos.
One Qiant - 82880282

1200
1200
60
60
X NN
30
40
X NN
60
X NN
X NN
✓
2500
8755.5
7000

Date of accident : 25/03/2021 01:30 PM. Place : YIO CHU KANG TOWARD SENGKANG ROAD

E. & O. E.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

CUSTOMER SIGNATURE

CAR CITY AUTO CENTRE PTE LTD

AUTHORISED SIGNATURE

* N = Item not subjected to GST
Acknowledged by Repairer

Service Centre Signature:
Blk 9006 Tampines Street 93
#01-198 Singapore 228840
Tel: 6781 0300 Fax: 6782 0300
24 Hrs Helpline: 9621 4666
Email: ccacpl@singnet.com.sg

Issued by : Ho