

PARTS	LABOUR		S/N	CHECK ITEM	SKX 2041L
754.3	50	1600	30		TOTAL
52.2	60		40		
47.73	120		40		11507.2625
47.73	120		100		0.8
243.7	80				9205.81
569.2	120				
382.1	200				
35.8	140				LUMP SUM
69.61	30				9200
169.39	60				
823.46	2480				
6.96		supp	supp labour		TOTAL CHECK ITEM
106.8	81.1				0
492.2	65				
58.7					
361.6					
179					
184					CHECK ITEM LABOUR
14.4					
319.5					
66.7					
581.2					
184.2					0
29.5					
818.1					
267					
855.82					
154					
95.47					
89.5					
75.58					
34.8					
8316.35	5060	0	0	0	
0.75		0.8		0.8	
6237.2625	210	0		0	