

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3021/03/21

Your Ref:

Date: 29th March 2021

MR TEO HOCK GUAN
BLK 251, #12-292,
CHOA CHU KANG AVE 2
SINGAPORE 680251

Estimate cost of repair to TOYOTA COROLLA ALTIS 1.6 (A) Saloon - SKX 2041 L

1 pc boot lid		\$ 754.30
1 pc boot lid logo emblem		52.20
1 pc boot lid 'COROLLA' emblem		47.73
1 pc boot lid 'ALTIS' emblem		47.73
1 pc boot lid chrome moulding		332.90
2 pcs o/s & n/s licence lamp assy	@ \$ 65.63	131.26
1 pc boot lid lock key less sensor		119.34
2 pcs boot lid o/s & n/s reflector	@ \$ 284.60	569.20
1 pc boot lid lock		382.10
1 pc boot lid lock stricker		35.80
2 pcs boot lid o/s & n/s hinge	@ \$ 69.61	139.22
1 pc boot lid inner garnish		308.29
10 pcs boot lid inner garnish clips	@ \$ 6.96	69.60
1 pc boot lid reverse camera		580.00
1 pc boot lid weatherstrip		169.39
2 pcs o/s & n/s tail lamp assy (With Gasket)	@ \$ 411.73	823.46
2 pcs o/s & n/s tail lamp clips stopper	@ \$ 6.96	13.92
2 pcs o/s & n/s tail lamp panel	@ \$ 106.80	213.60
1 pc rear bumper		492.20
10 pcs rear bumper clips	@ \$ 5.87	58.70
1 pc rear bumper reinforcement		361.60
2 pcs rear bumper damper	@ \$ 55.69	111.38
2 pcs rear bumper o/s & n/s top retainer	@ \$ 89.50	179.00
2 pcs rear bumper o/s & n/s side retainer	@ \$ 104.40	208.80
2 pcs rear bumper o/s & n/s side bracket clips	@ \$ 7.20	14.40
2 pcs rear bumper o/s & n/s reverse sensor		367.96
2 pcs rear bumper o/s & n/s sensor stopper	@ \$ 12.50	25.00
2 pcs rear bumper o/s & n/s reflector	@ \$ 66.70	133.40
1 pc rear end panel		581.20
1 pc rear end panel top garnish		229.40
5 pcs rear end panel top garnish clips	@ \$ 6.96	34.80
1 pc rear end panel lock stricker garnish		29.50
1 pc rear floor board panel		839.80
1 pc rear floor board cover		298.35
1 pc rear floor board panel insulator		65.00
1 pc rear n/s fender		855.82
14 pcs rear fender inner garnish clips	@ \$ 6.96	97.44
1 pc rear n/s fender inner garnish		288.40
1 pc rear n/s fender airscoop grille		95.47
1 pc rear bumper reinforcement bracket (n/s)		89.50
1 pc rear n/s fender wheel guard		75.58
5 pcs rear n/s fender wheel guard clips	@ \$ 6.96	34.80
1 pc rear end panel key less sensor		144.20
1 pc rear n/s chassis frame member		1,326.00

\$ 11,827.74

Balance C/F.....

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3021/03/21

Your Ref: _____

Date: 29th March 2021

MR TEO HOCK GUAN.,

Balance B/F... \$ 11,827.74

1 pc rear windscreen glass outer moulding	144.85
1 pc rear windscreen glass inner damper	75.00
1 pc rear windscreen glass sealant	60.00
1 pc fuel tank lid panel	89.50
2 pcs fuel tank lid rivets	@ \$ 35.80 71.60
1 pc fuel tank lid cable holder (with cap)	14.93
1 pc fuel tank grove cover garnish	99.45
1 pc fuel tank pipe	358.02
1 pc rear n/s door	954.72
1 set rear n/s door frame sticker	45.74
1 pc rear n/s door inner lock	358.02
1 pc rear n/s door inner lock stricker	49.78
12 pcs rear n/s door inner trim board clips	@ \$ 6.96 83.52
1 pc rear n/s shock absorber shaft	139.23
1 pc rear n/s lower arm	1,594.12
1 pc rear n/s wheel tyre	320.00
1 pc fuel tank	775.71

\$ 17,058.93

Less 25% \$ 4,264.73

\$ 12,794.20

1 pc rear number plate	40.00 S.N
1 set body sealant	100.00 S.N

To diagnose & re-set ABS sensor & fault code. 150.00

To check & adjust wheel alignment & balancing. 150.00

Towing charge (King Dolly) attach bill 120.00

To remove & refix rear windscreen glass & necessary parts. 150.00

To remove & refix fuel tank, hose, pipe & necessary parts. 180.00

To remove & refix rear cushion seat, carpet, floor mat, garnish, floor board cover, tool set, spare tyre & necessary parts. 150.00

To remove & refix rear n/s door inner trim board cover, glass, regulator, motor, moulding, weatherstrip, hinge, inner lock & necessary parts into new door. 120.00

To remove & refix rear n/s shock absorber shaft, lower arm, wheel hub, ABS system, bearing & necessary parts. 200.00

To respray Tuff-Kote on all affected accident parts. 180.00

\$ 14,334.20

Balance C/F.....

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3021/03/21 Your Ref: _____ Date: 29th March 2021

MR TEO HOCK GUAN.,

Balance B/F.... \$ 14,334.20

To remove & refix wiring system, including wiring check up
for affected wiring system. 60.00

To jack, straighten & knocking out rear exhaust & tail pipe. 150.00

Labour charge to remove & cut out damaged parts, to jack,
straighten & knocking out rear o/s fender, rear floor board
panel & necessary parts, to weld, renew & align above parts. 2,500.00


To jack, straighten & knocking out rear n/s chassis fame. 380.00

To putty & respray painting on all affected accident parts. 2,500.00

\$ 19,924.20
=====

Dollars : Nineteen Thousand Nine Hundred Twenty Four And Cents Twenty Only.

HUP MOTOR TRADING & SERVICE

.....



INSURER ENQUIRY

Find
insurer

Vehicle reg. no.

SMS2568L

Date of Accident

28/03/2021 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance MSIG Insurance (Singapore) Pt...

Period of Insurance 08/08/2020 - 07/08/2021

Requested By sandy (Hup Motor Trading & S...

Requested Date 28/03/2021 14:43

Payment details

Request Amount: **S\$1.87**

GST Amount: **S\$0.13**

Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	29/03/2021 13:47 (SGT)
Date of Accident	28/03/2021 12:50 (SGT)
Exact Location of Accident	Near 1B Royal Rd, Singapore 118303
Additional Location Information	SLIP RD OF ROYAL RD TOWARDS A.Y.E
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX2041L
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TEO HOCK GUAN
NRIC No	SXXXXX588D
Email Address	hgteo.hf@gmail.com
Mobile Phone No	(Phone) +65-96926336
Alternative Phone No	+65-96926336

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1598

INSURANCE COMPANY

Name of Insurance Company	India International Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	D19MPC0005425_01
Cover Note Number	-

DRIVER

Name of Driver	LIM YUAN SHEN
NRIC No	SXXXXX321H

Date Of Birth	17/07/1987
Occupation	Indoor
Date Of Driving Pass	06/05/2014
Driving experience	6 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-92299379
Alt. Phone Number	-
Email Address	YSLIMSG@GMAIL.COM
Address	BLK 807B CHOA CHU KANG AVE 1 #16-526
Address complement	-
Postcode	682807
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Child
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	5
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	TEO HOCK GUAN
Gender	Male

PASSENGER 2

Name	TEO XIN YI
Gender	Female

PASSENGER 3

Name	TAN YAN LING
Gender	Female

PASSENGER 4

Name	LIM YAN ZHENG
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

KINDLY REFER TO SKETCH PLAN ATTACHED.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMS2568L
Vehicle Manufacturer	Toyota
Vehicle Model	Sienta
Vehicle Variant	-
Vehicle Colour	White
Vehicle Category	Private hire
Name of Driver	SEAH BENG HUAT
NRIC No	SXXXX385G
Contact Number	(Phone) +65-96311035
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	3

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	TAN YAN LING
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SKX2041L
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

INJURED 2

Name of injured person	TEO XIN YI
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SKX2041L
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]
Policyholder's Signature / Date & Time

[Signature] 29/3/11 11:30 AM
Driver's Signature (If driver is not the policyholder) / Date & Time

[Signature]
Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

On 28 Mar 2021 around 12.50 pm. On Royal Road towards AYE, I slowed down before the white dotted line to give way to an oncoming white lorry on the right. After stopping Car B (#3MS25081) hit onto my rear.

15 mins later, 4 traffic police motorbikes and 2 ambulances arrived. 2 passengers sustain slight injury and was checked on the ambulance. Advise was given by the medic to observe and to go to hospital if injury worsen.

Due to the impact hit by Car B, my Car was unable to be driven. EMS was on site to facilitate an towing of the Car to the next exit.

<p>You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.</p>	Reporting Only
	Claim OD
	Claim TP <input checked="" type="checkbox"/>
	Claim OD / TP at other workshop

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre
Personnel

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

All Accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

CERTIFICATE NO.: D19MPC0005425_01

COVER: COMPREHENSIVE

1. **Index Mark and Registration Number of Vehicle** : SKX2041L
Chassis No : MR053REH104542566
2. **Name of Policyholder** : TEO HOCK GUAN
3. **Effective date of Insurance** : 30 Nov 2020
4. **Expiry date of Insurance** : 29 Nov 2021
5. **Persons or Classes of Persons entitled to drive***
 - (a) The Policyholder
The Policyholder may also drive a Motor Car not belonging to or hired (under a hire purchase agreement or otherwise) to him/her or his/her employer or his/her partner.
 - (b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle
6. **Limitations as to use***
Use only for social, domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover
 - a) Use for hire or reward.
 - b) Use for racing, pace-making, reliability trial, speed-testing.
 - c) Use for the carriage of goods other than samples in connection with any trade or business.
 - d) Use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Insured & Named Driver Excess Sect I : SGD600.00
Unnamed Driver Excess Sect I : SGD1100.00
Windscreen Excess : SGD100.00


Hire Purchase Company : Hong Leong Finance Limited

FOR DRIVERS BELOW 21 YEARS OR ABOVE 65 YEARS OF AGE &/OR LESS THAN 2 YEARS SINGAPORE DRIVING LICENCE, ADDITIONAL EXCESS OF \$2500/- ON SECTION I WILL BE APPLICABLE.

I/We HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Agent/Broker : A000038/M Plus Consultancy
Date of Issue : 05/10/2020 17:00:02
MX1-Private Car (Insured Driving)

For India International Insurance Pte Ltd



 Authorised Signatory

Vehicle Details	
Vehicle No.:	SKX2041L
Make / Model:	TOYOTA / TOYOTA COROLLA ALTIS 1.6L CVT
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Chassis No. :	MR053REH104542566
Propellant :	Petrol
Engine No. :	1ZRY236311
Motor No. :	-
Engine Capacity :	1598 cc
Power Rating :	-
Maximum Power Output :	90.0 kW (120 bhp)
Maximum Laden Weight :	1640 kg
Unladen Weight :	1205 kg
Year Of Manufacture :	2015
Original Registration Date :	30 Nov 2015
Lifespan Expiry Date :	-
COE Category :	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium :	\$57,089.00
COE Expiry Date :	29 Nov 2025
Road Tax Expiry Date :	29 Nov 2021
PARF Eligibility Expiry Date :	29 Nov 2025
Inspection Due Date :	29 Nov 2022
Intended Transfer Date :	28 Mar 2021
CO2 Emission :	151.00 (g/km)
CEV/VES Rebate Utilised Amount :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Fees To Be Paid For Transfer	
Transfer Fees	\$25.00