

SERVICE ESTIMATE

71384 - C00001
Mr Han Chung Heng
30 Kew Heights

SL: SERVICE SALES - PC

Singapore 466087

Closed by : Juan Paulo Bongon Ba
Svc Consultant : *98270463*
Remarks : Mr Han Chung Heng

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 29/03/2021
WIP No. . : 17664
Veh.In/Out:
*Tel.No. . : Mobile: 86114848 Mrs
Reg.No. . : SMD179T
Reg.date . : 30/07/2018
Mileage ... : 0
Chassis No: SAJAC12M9HPW05396

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE BOOTLID, 1000 x 2	0	<i>2000</i> 3500.00	0		3,500.00	S
	REAR BUMPER, REAR REINFORCEMENT,						
	REAR UNDERTRAY, TAIL LAMP LH/RH,						
	ETC						
800	TO SPRAY BOOTLID, 900 x 2	0	<i>1800</i> 5000.00	0		5,000.00	S
	REAR BUMPER, REAR REINFORCEMENT,						
	REAR FENDER LH/RH.						
802	TO REMOVE & REFIT, TRANSFER	0	600.00	/0		600.00	S
	BOOTLID INTERIOR COMPONENTS.						
802	TO REPLACE REAR EXHAUST	0	1100.00	X0		1,100.00	S
	MUFFLER						
280	TO CHECK WIRING INCLUDE	0	621.00	/0		621.00	S
	RESETTING OF ALL ELECTRICAL						
	MODULES						
R06	NUMBER PLATE & HOLDER	0	60.00	/0		60.00	S
	COVER-BUMPER <i>00</i>	1.0 EA	2666.00			2,666.00	S
	BUMPER BRACKET REAR <i>1</i>	1.0 EA	44.90			44.90	S

*Steve (LKK) will be
30/3/21, 10.11a
4 days
P/P
by B.L. sy*