

SERVICE ESTIMATE

71364 - C00001
Mr Han Chung Heng
30 Kew Heights

SL: SERVICE SALES - PC

Singapore 466087

Closed by : Juan Paulo Bongon Ba
Svc Consultant : ACC
Remarks : Mr Han Chung Heng

GST Reg.No:M28920628X
Inv.No. . . : B&P 0 Page 1
Inv.date. . : 22/04/2021
WIP No. . . : 17664
Veh.In/Out: 21/04/2021
*Tel.No. . . : Mobile: 86114848 Mrs
Reg.No. . . : SMD179T
Reg.date . . : 30/07/2018
Mileage ... : 56,016
Chassis No: SAJAC12M9HPW05396

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR END PANEL, REAR REINFORCEMENT, ETC	0	3250.00	/0		3,250.00	S
800	TO SPRAY REAR END PANEL,	0	1000.00	/0		1,000.00	S
802	TO REMOVE & REFIT SIDE TRIMS, EXHAUST TO FACILITATE REPAIR.	0	1000.00	/0		1,000.00	S
	BUMPER BEAM REAR XJL 1352.25	1.0 EA	1502.50	- dh		1,502.50	S
	INNER PANEL REAR XJL 3217.77	1.0 EA	3575.30	- DD		3,575.30	S
	3M07333 IMPACT RESIS 75.69	1.0 EA	84.10	- nec		84.10	S
	RIVET 6.5X13X20 XJL 55.80	10.0 EA	6.20	- nec		62.00	S
	RIVET FSC4850 4.8X5 27.00	10.0 EA	3.00	- nec		30.00	S
	RIVET FSC4870 4.8X7 10.80	5.0 EA	2.40	- nec		12.00	S
	RIVET 6.5X13X16 XJL 57.60	40.0 EA	1.60	- nec		64.00	S

Gross Total. 10,579.90
Net..... 10,579.90
GST @ 7.0% 740.59
Total..... 11,320.50
Paid..... 0.00
Please Pay.. 11,320.50

Labour Total 5,250.00
Parts Total 5,329.90
Package Total 0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated