

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL		Ref:	CS/AGI21004020/Ktf3q2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE		Date:	06/04/2021	
				Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLK 1277L	Veh. Inspected		SHD 9402Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10009584/CH	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		29/03/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PRIUS (A)	c.c		1798	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JTDKB3FU303079466	Colour		M . P. WHITE / RED	
	Odometer	180422 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	SAILUN		9 mm	
	L/H Front Tyre	195/65 R15	SAILUN		9 mm	
	R/H Rear Tyre	195/65 R15	SAILUN		9 mm	
	L/H Rear Tyre	195/65 R15	SAILUN		9 mm	
4.		Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE D	DAMAGES SEE DETAILS.				
5.	•	General Information				
	Accident Date	27/03/2021	Inspection Date	•	30/03/2021	
	Survey held at	at TRANS-CAB AUTO SERVICES PTE LTD				
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111				
5a.		Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

1.500 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: