

Survey
31/2/2021
13 hrs
Terima
Muz

Re Survey
6/4/2021
1455 hrs
Terima
Muz

BIFROST AUTO

8 KAKI BUKIT AVE #01-49, PREMIER @ KAKI BUKIT,
SINGAPORE 415875

Estimate for SMY6699J (Audi Q5)

Qty	Spare Parts	List Price (\$)
1	Tailgate	\$ 3318.25 3929.00 DDV
1	Tailgate windscreen glass with rubber moulding seal	\$ 397.30 1033.00 NECV
1	Tailgate centre emblem	\$ 113.00
1	Tailgate "Q5" emblem	\$ 87.00
1	Tailgate "Quattro" emblem	\$ 87.00
1	Tailgate lock	\$ 184.00 NDX
1	Tailgate lock catch	\$ 45.00 NDX
1	Tailgate inner trim board	\$ 263.00 NDX
1 set	Tailgate inner trim board clips	\$ 20.00 80.00 NECV
1	Tailgate weatherstrip	\$ 284.00 NDX
1	Rear bumper (upper)	\$ 1571.00 BRV
1	Rear bumper (lower)	\$ 1077.00 MISV
1	Rear bumper spoiler	\$ 368.00 NSX
1	Rear bumper RH side reverse sensor	\$ 200.00 231.00
1	Rear bumper RH reverse sensor	\$ 200.00 231.00
1	Rear bumper LH reverse sensor	\$ 200.00 231.00
1	Rear bumper LH side reverse sensor	\$ 231.00 NDX
3	Rear bumper reverse sensor ring seals	\$ 9.00 12.00 NECV
1	Rear bumper reverse sensor wire harness	\$ 153.00 NDX
1	Rear bumper RH tow cover	\$ 43.00 MISV
1	Rear bumper LH tow cover	\$ 43.00 BRV
1	Rear bumper RH lamp assy	\$ 289.90 343.00 BRV
1	Rear bumper LH lamp assy	\$ 289.90 343.00
1	Rear bumper reinforcement	\$ 248.25 834.00 STV
1	Rear bumper RH side bracket	\$ 54.00
1	Rear bumper LH side bracket	\$ 54.00
1	Rear RH fender wheel arch moulding	\$ 298.00 482.00 BRV
1	Rear LH fender wheel arch moulding	\$ 298.00 482.00
1	End panel	\$ 524.00 DDX R
1	End panel inner trim	\$ 113.00 NDX
1	Exhaust silencer	\$ 1254.00
1	Exhaust silencer heat shield cover	\$ 260.00 384.00 DDV
1	Exhaust silencer gasket	\$ 55.00 NECV

11576.60
@ 5% 578.83
10997.77

\$	10,137.00
\$	506.83
\$	9,630.17



BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE #01-49, PREMIER @ KAKI BUKIT.

SINGAPORE 415875

Estimate for SMY6699J (Audi Q5)

Supplementary

Qty Spare Parts

List Price (\$)

2	Exhaust silencer rubber hangers	\$	20.30 NSX
1	Exhaust RH heat shield cover	\$	✓ 238.45 PDV
1	Rear crossmember	\$	3065.00 3,286.00 BTV
1	Rear RH lower arm	\$	✓ 623.95
1	Rear RH knuckle arm	\$	✓ 1,019.80 } BTV
1	Rear RH control arm	\$	237.60 344.58 }
1	Rear RH upper arm	\$	✓ 458.28
1	Rear RH wheel bearing	\$	555.85 NDX
1	Rear LH lower arm	\$	623.95
1	Rear LH knuckle arm	\$	1,019.80
1	Rear LH control arm	\$	344.58
1	Rear LH upper arm	\$	458.28
1	Rear LH wheel bearing	\$	555.85 } NDX
1	Charcoal Canister	\$	352.78

5643.08
 @ 5% 282.15
 5360.93

~~5443.08~~
~~5079.77~~

5% \$ 9,970.85
 -10% \$ 997.09 -5%
 \$ 8,973.77

Labour and painting

Remove and replace rear undercarriage parts	\$	1100.00 1100.00 ✓
Conduct and adjust wheel alignment system	\$	60.00 100.00 ✓
Towing fee	\$	50.00 NDX

Total: \$ 9,623.77 10,122.31

~~5538.77~~
 5360.93
 460.00
 5820.93

Qty	Spare parts	Special Nett (\$)
1	Tailgate windscreen glass sealant	\$ 50.00 20.00 MELV
1	Tailgate windscreen glass inner seal	\$ 60.00 NSX

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut / weld and re-align all affected panels	\$ 500.00	1,000.00 ✓
Spray painting on affected panels	\$ 600.00	1,200.00 ✓
Check wiring and lighting system	\$ 50.00	80.00 ✓
Replace tailgate windscreen glass and sealants	\$ 120.00	180.00 ✓
Transfer, check and replace tailgate inner components to new tailgate	\$ 90.00	100.00 ✓
Remove and replace rear inner trims, garnish and boards to assist repairs	\$	250.00 NNX
Remove, check and replace rear bumper reverse sensors and wire harness to assist repairs	\$ 60.00	80.00 ✓
Remove, replace and realign exhaust silencer, rubber hangers, heat shield cover and centre pipe to assist repairs	\$ 120.00	180.00 ✓
Apply anti rust coating on affected areas	\$ 60.00	80.00 ✓
Diagnose and reset fault code after repaired	\$ 120.00	250.00 ✓

Lump sum repair

Repair days 8

Total: \$ 13,150.15 23,272.46

16818.70	PARTS	16076.54
50.00	S/N	50.00
<u>2170.00</u>	LABOUR	1710.00
18,578.70		17836.54
<u>3,715.74</u>	@ 20%	3567.31
14,862.96		14219.23
1/0 14,250/2		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Amended L/S 14,850.00

TGrim *[Signature]* 5/5/2021