



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL

INV No. AC2102489

50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWER
SINGAPORE 048623

INV Date 12/04/2021
Reference CS3/SMO21004056/Uvf3e2
Code SMO

PROFESSIONAL SERVICE FEE

Vehicle No. GBJ 6818S
Insured Veh. GBE 3920A
Claim No. CMTD2100932/MYE
Policy No.
Accident Date 24/03/2021
Inspection Date 07/04/2021

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 07.04.2021)	60.00
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM