



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:GARNET LOW			Ref: CC4/ASM21004109/Apa3q2 Date: 05/08/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6590H	Veh. Inspected	SJM 4517M	
Policy No.	P2426680	Coverage (\$)	0.00	
Claim No.	S1M036NA	Excess (\$)	0.00	
Assign From		Assign Date	30/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI LANCER		c.c	1584
Engine No.	HIDDEN		Year of Reg.	2009
Chassis No.	JMYSNCS3A8U007556		Colour	BLUE
Odometer	186119 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre	195/50 R15		TOURADOR	6 mm
L/H Front Tyre	195/50 R15		TOURADOR	6 mm
R/H Rear Tyre	195/50 R15		TOURADOR	6 mm
L/H Rear Tyre	195/50 R15		TOURADOR	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/03/2021		Inspection Date	30/03/2021
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	