



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA			Ref: CC4/ASM21004110/Gga3q2 Date: 20/04/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 3214A	Veh. Inspected	SLF 2970M
	Policy No.	P2419140	Coverage (\$)	0.00
	Claim No.	S1M036PE	Excess (\$)	0.00
	Assign From		Assign Date	30/03/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA WISH	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JTDGG20WX0J004884	Colour	BLUE
	Odometer	297429 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	GRENLANDER	6 mm
	L/H Front Tyre	195/65 R15	GRENLANDER	6 mm
	R/H Rear Tyre	195/65 R15	GRENLANDER	6 mm
	L/H Rear Tyre	195/65 R15	GRENLANDER	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/03/2021	Inspection Date	26/04/2021
	Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	