

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG21004136/R1VF3E2  
**Date:** 03/05/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070106271
<b>Claimant Vehicle No :</b>	SGG4991T	<b>Insured Vehicle No :</b>	SMT7613B
Date of Loss:	27/03/2021	Nature of Claim:	TP
		Claim No:	0492098602SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGG4991T</b>	Engine No:	1ZZ2557872
Make & Model:	TOYOTA WISH, 1.8 X (A)	Chassis No:	ZNE100304208
Reg. Date:	15/05/2006 (Man. Year: 2006)	Odometer:	251420 km
Colour:	Blue		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	30/03/2021		
Date Inspected:	31/03/2021	Inspected At:	Toy Carz Auto Roaming (HQ) 210 TURF CLUB ROAD LOT B70 & 71 THE GRANDSTAND Singapore 287995
Estimated Period of Repair:	0.0 days		

**Adjuster:** MOHD RASUL

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value : \$800.00

OMV : \$21,282.00

PARF Rebate (1) : \$0

Quota Premium Paid : \$1423,024.00

COE Rebate (2) : \$559.00

Total Rebate (1) + (2) = : \$241.00

The total amount incurred will be Market Value \$800.00 minus Total Rebate \$559.00 = \$241.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

# REPAIR DETAILS

## Recommended Parts

There are no new parts selected.

LKK Auto Consultants Pte Ltd/SGG4991T/03/05/2021 09:43
--

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

LKK Auto Consultants Pte Ltd/SGG4991T/03/05/2021 09:43
--

< END OF ESTIMATES >