



Your Ref : 0492098602SG

Date: 13th April 2021

Our Ref : CS/AIG21004136/R1vf3e2

M/s AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #09-16

AIG Building

Singapore 079120

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGG 4991T
INSURED VEHICLE: SMT 7613B
ACCIDENT ON 27/03/2021**

Instruction was received to inspect the vehicle Reg. No. SGG 4991T. The inspection was conducted on 27/03/2021 at the premises of M/s Toy Carz Auto Roaming, 210 turf club road lot B70 & 71 the grandstand, Singapore 287995.

The following vehicle information was recorded:

Registration Number	: SGG 4991T
Make/Model	: Toyota Wish 1.8X A
Year of Registration	: 2006
Body Colour	: Blue
Chassis Number	: ZNE100304208
Engine Capacity	: 1794 cc

The vehicle sustained damages at the rear portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 800.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 559.00)
Nett Liability	<u>S\$ 241.00</u> =====

Vehicle Inspected By:



MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.