

# RICO60

Auto Services

Rico 60 Auto Services Pte Ltd  
 Blk 8 , Kaki Bukit Avenue 4 , #02-24  
 Premier @ Kaki Bukit Singapore 415875  
 Email: claims@rico60.com  
 Tel: 6286 6060 Fax : 6286 7060

### RICO Office Use Only

Parts -25%	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	

TO: CHINA TAIPING

Vehicle No : GBK 9197 A

Make & Model : TOYOTA DYNA

DATE: 22/3/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	FRONT DOOR RH	1	\$ 1,794.20	\$ <del>By</del> 1,794.20
2	FRONT DOOR OUTER MOULDING RH	1	\$ 159.80	\$ <del>xm</del> 159.80
3	FRONT DOOR OUTER HANDLE RH	1	\$ 277.50	<del>xm</del>
4	FRONT DOOR HINGE RH	2	\$ 120.00	\$ <del>xm</del> 240.00
5	FRONT DOOR CHECKER RH	1	\$ 136.50	\$ <del>xm</del> 136.50
6	FRONT DOOR INNER LOCK RH	1	\$ 396.40	\$ <del>xm</del> 396.40
7	FRONT DOOR LOCK CATCH RH	1	\$ 46.00	\$ <del>xm</del> 46.00
8	FRONT DOOR WEATHERSTRIP RH	1	\$ 198.00	\$ <del>xm</del> 198.00
9	FRONT DOOR REGULATOR MOTOR RH	1	\$ 475.90	\$ <del>xm</del> 475.90
10	FRONT DOOR REGULATOR GEAR RH	1	\$ 321.00	\$ <del>xm</del> 321.00
11	FRONT DOOR FRAME WEATHERSTRIP RH	1	\$ 254.00	\$ <del>xm</del> 254.00
12	FRONT DOOR SIDE RUBBER RH	1	\$ 100.00	\$ <del>xm</del> 100.00
13	FRONT DOOR BOTTOM RUBBER RH	1	\$ 100.00	\$ <del>xm</del> 100.00
14	FRONT DOOR LOWER STEP GARNISH RH	241.40	\$ 498.70	\$ <del>cut</del> 498.70
15	CABIN REAR PILLAR RH	1	\$ 693.50	\$ <del>Rp</del> 693.50
16	CABIN REAR PILLAR EMBLEM (D4D)	1	\$ 96.80	\$ <del>req</del> 96.80
17	FRONT MUDGUARD RH	225	\$ 374.20	\$ <del>cut</del> 374.20
18	FRONT ABSORBER RH	1	\$ 207.70	\$ <del>xm</del> 207.70
19	FROTN ABSORBER TOP MOUNTING RH	1	\$ 90.00	\$ <del>xm</del> 90.00
20	FRONT UPPER ARM RH	1	\$ 1,720.50	\$ <del>xm</del> 1,720.50
21	FRONT LOWER ARM RH	1	\$ 1,029.60	\$ <del>xm</del> 1,029.60
22	FRONT KNUCKLE ARM RH	421	\$ 518.70	\$ <del>* Bt</del> 518.70
23	FRONT WHEEL BEARING RH	1	\$ 128.70	\$ <del>* Bt</del> 128.70
24	AIR CLEANER BOX ASSY	494.70	\$ 876.40	\$ <del>cm</del> 876.40
25	RADIATOR SPARE TANK	140.90	\$ 224.50	\$ <del>cut</del> 224.50
26	SIDE GATE RH	1325.40	\$ 1,898.60	\$ <del>bt</del> 1,898.60

27	SIDE GATE FRONT HANDLE LOCK RH		1	\$ 216.00	\$ <del>216.00</del> 216.00
28	SIDE GATE FRONT HANDLE LOCK BRACKET RH		1	\$ 225.30	\$ <del>225.30</del> 225.30
29	SIDE GATE HINGE RH	(150) 3.8		\$ 50 90.00	\$ <del>540.00</del> 540.00
30	SIDE GATE BOTTOM PANEL RH	454.70	1	\$ 752.40	\$ <del>752.40</del> 752.40
31	SIDE GATE BOTTOM STEP PANEL RH	155	1	\$ 244.30	\$ <del>244.30</del> 244.30
32	TAIL GATE LOWER SIDE RAILING RH	Rear RH	1	\$ 246.00	\$ <del>246.00</del> 246.00
33	TAIL GATE LOWER SIDE RAILING STOPPER RH		1	\$ 38.50	\$ <del>38.50</del> 38.50
34	REAR MUDGUARD RH	225	2	\$ 372.40	\$ <del>744.80</del> 744.80
35	REAR MUDGUARD BRACKET RH	(100) 2	4	\$ 50 70.00	\$ <del>280.00</del> 280.00
36	TAIL LAMP RH		1	\$ 354.00	\$ <del>354.00</del> 354.00
37	TAIL LAMP BRACKET RH		1	\$ 172.40	\$ <del>172.40</del> 172.40
38	DIESEL TANK	745.11	1	\$ 1,278.90	\$ <del>1,278.90</del> 1,278.90
39	DIESEL TANK BELT	(320) 1000	2	\$ 160 233.50	\$ <del>467.00</del> 467.00
40	DIESEL TANL BELT BRACKET	255.60	2	\$ 417.00	\$ <del>834.00</del> 834.00
41	REAR ABSORBER RH		1	\$ 580.00	\$ <del>580.00</del> 580.00
42	REAR WHEEL BEARING RH		1	\$ 790.00	\$ <del>790.00</del> 790.00
43	REAR AXLE BEAM		1	\$ 2,245.00	\$ <del>2,245.00</del> 2,245.00

5863.70  
 4397.77  
 Subtotal : \$ 17,077.50  
 Less 25% \$ 4,269.38  
 Parts Total : \$ 12,808.13

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	FRONT DOOR COMPANY STICKER <i>net</i>	1	\$ 300.00	\$ 150 300.00
2	FRONT DOOR COMPANY LETTERING <i>net</i>	1	\$ 60.00	\$ 40 60.00
3	CABIN REAR PILLAR SEALANT	1	\$ 80.00	\$ <del>80.00</del> 80.00
4	RADIATOR COOLANT <i>nec</i>	1	\$ 60.00	\$ 40 60.00
5	FRONT MUDGUARD CLIP <i>nec</i>	1	\$ 50.00	\$ 60 50.00
6	FRONT MUDFLAP RH	1	\$ 200.00	\$ <del>200.00</del> 200.00
7	REAR MUDGUARD CLIP	1	\$ 50.00	\$ <del>50.00</del> 50.00
8	REAR MUDGUARD MUDFLAP	2	\$ 40.00	\$ <del>80.00</del> 80.00
9	FORNT RIM RH	1	\$ 250 450.00	\$ <del>450.00</del> 450.00
10	FRONT TYRE RH	1	\$ 350.00	\$ <del>350.00</del> 350.00
11	REAR TYRE RH	1 2	\$ 120 300.00	\$ <del>600.00</del> 600.00
12	REAR RIM RH <i>cut</i>	1 2	\$ 150 350.00	\$ 700.00
13	SIDE GATE COMPANY STICKER <i>net</i>	1	\$ 300 600.00	\$ 600.00
14	SIDE GATE TOP RAILING BAR	1	\$ 1,500.00	\$ <del>1,500.00</del> 1,500.00
15	SIDE GATE INNER ALUMINIUM PLATE	1	\$ 800.00	\$ <del>800.00</del> 800.00
16	RIVET <i>net</i>	1	\$ 150.00	\$ 100 150.00

1160

