

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0274/2021/HR
DATE : 1-Apr-21
WIP : 21627

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/4/21

YOUR INSURED VEH NO : YM 8468 S

LONPAC INSURANCE BHD

300, Beach Road

#17-04 The Concourse

SINGAPORE 199555

Motor Claims Dept

Tel: 6223 9433 - Fax: 6223 4191

OWNER'S NAME : MR.PANG SHENG DONG
ADDRESS : BLK 6 COVE WAY
SINGAPORE 098274
TELEPHONE : HP +65 97510851
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100432641-05
VEHICLE NO : **SKW 2345 R**
MODEL CODE : Q7 3.0 TFSI QU
MODEL YEAR : 27/2/2020
ENGINE NO : CRE 048236
CHASSIS NO : WAUZZZ4M4GD010593
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Mar-21
PLACE OF ACCIDENT : GENTING LANE CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKW 2345 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$ 450.00 ✓	
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	S/N \$ 280.00 ✗ ✓	
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,700.00 ✓	900
5	TO RESPRAY FRONT BUMPER, RHS FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER, DOOR COVER AND BOTH WHEEL ARCH TRIM	\$ 5,000.00 ✓	Bumper, Fender : 1800 Rear Spoiler : 250 Wheel Arch x 2 : 600 Door Cover : 350
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 9,102.00	3000

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKW 2345 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>Dehurd</i>	1	\$ 2,724.00	✓
2	FRONT BUMPER FIXING PARTS <i>Meu</i>	1	\$ 447.00	+
3	FRONT BUMPER AIR GUIDE - INNER <i>xen</i>	1	\$ 67.00	+
4	FRONT BUMPER END CAP - RH <i>Meu</i>	1	\$ 36.00	+
5	FRONT BUMPER LOWER GRILLE - CENTER <i>Meu</i>	1	\$ 206.00	+
6	FRONT BUMPER CLOSING ELEMENT <i>Meu</i>	1	\$ 210.00	+
7	FRONT BUMPER SPOILER - RH <i>Regis</i>	1	\$ 211.00	+
8	FRONT BUMPER OUTER SPOILER - RH <i>Regis</i>	1	\$ 44.00	+
9	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Dangd</i>	1	\$ 297.00	✓
10	FRONT BUMPER AIR GUIDE GRILLE END CAP - RH <i>Meu</i>		\$ 34.00	+
11	FRONT BUMPER SPRING CLIP - RH <i>Meu</i>	1	\$ 4.00	+
12	FRONT BUMPER INNER SPOILER - RH <i>Meu</i>	1	\$ 59.00	+
13	FRONT BUMPER GUIDE SECTION <i>Meu</i>	1	\$ 44.00	+
14	FRONT BUMPER FOAM FILLER PIECE <i>3Meu</i>	1	\$ 171.00	+
15	FRONT BUMPER CARRIER	1	\$ 964.00	+
16	FRONT FENDER - RH <i>Regis</i>	1	\$ 1,620.00	+
17	FRONT FENDER ATTACHMENT PARTS - RH <i>xen</i>	1	\$ 76.00	+
18	FRONT FENDER BRACKET - RH <i>3Meu</i>	1	\$ 65.00	+
19	FRON FENDER BRACE - RH	1	\$ 101.00	+
20	"S-LINE" EMBLEM <i>xen</i>	1	\$ 128.00	✓
SUB TOTAL SPARE PARTS		:	\$ 7,508.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKW 2345 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL HOUSING LINER - SHORT / LONG - RH <i>3H</i>	2	\$ 480.00	+
22	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>1H</i>	1	\$ 183.00	+
23	FRONT WISHBONE LINK LH - LOWER <i>2H</i>	1	\$ 131.00	+
24	"CAUTION" STICKER <i>1H</i>	1	\$ 14.00	+
25	HEADLIGHT MOUNTING BEAM <i>1H</i>	1	\$ 118.00	+
26	HEADLIGHT - RH <i>1H</i>	1	\$ 12,792.00	✓
27	HEADLIGHT LIFT CYLINDER - RH <i>1H</i>	1	\$ 198.00	+
28	FRONT WHEEL COVER - 1H <i>2H</i>	2	\$ 1,150.00	✓
29	FRONT DOOR - RH <i>1H</i>	1	\$ 695.00	+
30	SUNDRIES <i>?</i>		\$ 350.00	?
TOTAL SPARE PARTS		:	\$ 23,619.00	
TOTAL LABOUR CHARGES		:	\$ 9,102.00	
GRAND TOTAL		:	\$ 32,721.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *05/04/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *the Authorized, 05 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT