Kaki Bukit Autohub, 2 Kaki Bukit Ave 2, #01-18

Singapore 417921

Tel No.: +65 6842 0051 / 6744 0510 Fax No.: +65 6741 0510

Company Reg. No.: 200616038C GST Registration No.: 200616038C

Our Ref:

SJM 7193 T

Your ref:

SMA 739 T

31 March 2021

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711

Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT: MUNCHI LEASING PTE LTD

VEHICLE NUMBER: SJM 7193 T

YOUR INSURED VEHICLE NUMBER: SMA 739 T

ACCIDENT ON 30 Mar 2021 ALONG VICTORIA LANE OUTSIDE MADRASAH ALJUNIED

AT ABOUT 07:20 HOURS

We refer to your email/fax dated **31 Mar 2021** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK Auto Consultants Pte Ltd** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub 2 Kaki Bukit Avenue 2 #01-18 Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!
Appointed surveyor:

(Name & Signature):

Date & Time of Inspection: