




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: TAN JUN HONG			Ref: CS3/ASM21004172/Gtce2 Date: 14/04/2021 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 2679T	Veh. Inspected	FBP 983E
	Policy No.		Coverage (\$)	0.00
	Claim No.	S1M035O8	Excess (\$)	0.00
	Assign From	TAN JUN HONG	Assign Date	31/03/2021
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA MTN850A	c.c	847
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JYARN435000021521	Colour	BLACK
	Odometer	-	Steering	JAMMED
	Brakes	JAMMED	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	120/70Z R17	BRIDGESTONE	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	180/55Z R17	BRIDGESTONE	4 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION.			
5. General Information				
	Accident Date	16/03/2021	Inspect Date / Time	01/04/2021 (04:30 PM)
	Survey held at	BIKES AND TEA PTE LTD 25 KAKI BUKIT ROAD 4, #01-43, SYNERGY @ KB, SINGAPORE 417800		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days

Report Ref No. CS3/ASM21004172/Gtce2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.