



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:RICHARD ANG

Ref: CC4/ASM21004155/Aba3q2
Date: 13/07/2021
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3339D	Veh. Inspected	SLQ 8851B
Policy No.	P2426680	Coverage (\$)	0.00
Claim No.	S1M036UB	Excess (\$)	0.00
Assign From		Assign Date	31/03/2021

2. Vehicle Particulars & Condition

Make & Model	NISSAN PULSAR	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VSKDDAC13U0104124	Colour	BLUE
Odometer	66381 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R17	TOURADOR	6 mm
L/H Front Tyre	205/50 R17	TOURADOR	6 mm
R/H Rear Tyre	205/50 R17	TOURADOR	6 mm
L/H Rear Tyre	205/50 R17	TOURADOR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/03/2021	Inspection Date	01/04/2021
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**