




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: DOMINIC YU			Ref: CS3/ASM21004243/Qtce2 Date: 15/04/2021 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHB 4606X	Veh. Inspected	SLQ 4704U
	Policy No.		Coverage (\$)	0.00
	Claim No.	S1M036Z1	Excess (\$)	0.00
	Assign From	DOMINIC YU	Assign Date	01/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3 SEDAN	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JM6BN22A8H0167465	Colour	BLUE
	Odometer	44480 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	TOYO	6 mm
	L/H Front Tyre	205/60 R16	TOYO	6 mm
	R/H Rear Tyre	205/60 R16	TOYO	6 mm
	L/H Rear Tyre	205/60 R16	TOYO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information				
	Accident Date	26/03/2021	Inspect Date / Time	07/04/2021 (10:56 AM)
	Survey held at	ANN JOO MOTOR PL BLK 176 SIN MING DRIVE #02-17 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days

Report Ref No. CS3/ASM21004243/Qtce2

Inspected By

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.