

pv.
\$190,000

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT21/PC9332C/TPC

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PC9332C

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)	
1.	Rear tailgate / pb	1	3,800.00	3,800.00	2,800
2.	Rear tailgate inner structure frame / bp	1	1,850.00	1,850.00	1,550
3.	Rear tailgate grille / Nec.	1	550.00	550.00	✓
4.	Rear tailgate center lock / Jam	1	588.00	588.00	388
5.	Rear tailgate hinges / BT	2	385.00	770.00	560
6.	Rear tailgate gas spring X svc	2	170.00	340.00	X
7.	Rear tailgate inner sensor 2 / Mis. / 1/2	1	230.00	460.00	230
8.	Rear tailgate lock X svc	1	532.00	532.00	X
9.	Rear tailgate RH catch / BT	1	196.00	196.00	✓
10.	Rear bumper / Chy.	1	1,650.00	1,650.00	✓
11.	Rear bumper RH & LH bracket / BK	2	255.00	510.00	✓
12.	Rear bumper inner structure / BT	1	850.00	850.00	✓
13.	Rear RH taillamp panel outer fiber panel / Chy	1	1,430.00	1,430.00	1,254
14.	Rear RH taillamp assy / Sck	1	1,350.00	1,350.00	1,158
15.	Rear RH lower reflector 2 X svc	1	185.00	185.00	X

16.	Rear pulley ^{photo} ? X Svc	1	2,380.00	2,380.00 X
17.	Rear whole set electric wire & cables / Cpu	1	960.00	960.00 ✓
18.	ECU unit ? X Svc	1	8,000.00	8,000.00 X
19.	Exhaust bracket X X Svc	1	220.00	220.00 X 12,656
20.	Rear camera / show	1 S/N	350.00	350.00 220
21.	Rear number plate / Cpu	1 S/N	50.00	50.00 ✓
22.	60KM/H sticker / Nec	1 S/N	15.00	15.00 ✓ 285
23.	Check wiring	1	150.00	150.00 120
24.	Reset ECU unit	1	300.00	300.00 ? X
25.	Labour charges	1	2,400.00	2,400.00 2,100
26.	Spray painting with logo	1	2,400.00	2,400.00 1,400
27.	Towing fee X	1	250.00	250.00
SUB-TOTAL				SS32,536.00 3,620

- Price before 7% gst

Thank you.

Repair day 10 days

L/S


After paint photo

Sun Pm (Lili)

05/04/2021

TP with prejudice.

Yours faithfully



Winnie Chai
HP: 9850-9666

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12,656
- 10%
11,390.40
285
3,620
15,295.40
- 20%
12,236.32

L/S
\$12,250
10 days