



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address (AIG Asia Pacific Insurance Pte. Ltd.) and Owner Name & Vehicle Info (Cust No/Name, Reg No/Reg Date, Date In/Mileage, Chassis No, Engine No, Make/Model, Colour/Trim).

Summary row with columns: Account No (LAX00000), Terms (Credit), Date/Time Printed (05/04/2021/ 12:58), CSE (QUK), Operator (282 / Kevin Leong), WIP No (31468).

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes items like PNT88000 REPLACE REAR BUMPER, PAINT WORK ON REAR BUMPER, etc.

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for CHEE SHU HUI (ZHU SHUHUI).

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: LAX00000, Credit, 05/04/2021/ 12:58, QUK, 282 / Kevin Leong, 31468

Main table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various car parts and services with handwritten notes and a large 'Estimate' watermark.

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 ATG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /CHEE SHU HUI (ZHU SHUHUI) Reg No/Reg Date SMD9367H*ECB / 12/09/201 Date In/Mileage 03/04/2021/ 0 Chassis No KNAF3416MK5013618 Engine No G4FGJH703967 Make/Model KIA/CERATO 1.6 A SX G335 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	05/04/2021/ 12:58	QUK	282 / Kevin Leong	31468

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LAMP ASSY-CENTER GARNISH / CUT	1.00	690.00	20.00	552.00
M LAMP ASSY-REAR COMB INSIDE, RH / OR	1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB OUTSIDE, RH / OR	1.00	675.00	20.00	540.00

Estimate

5/4/21 2.00 pm
 Steve CLKK) 00- Not NL
 Excess - ?
 PIP
 My BL SJ
 9 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

Confirm & accepted by	Nett	14,602.40
	7% GST on 14602.40	1022.17
	Total Payable	15,624.57

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.