

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

LKK HSI 1407000

Not Appointed
the
8/4/21
1/5 @ 1500/
2 days.

VEHICLE No: SJX 4009E

1PC	FRONT DOOR N/S	<i>n</i>		\$922.10	X
1PC	FRONT DOOR PROTECTOR N/S	<i>neu</i>	245.20	\$266.80	—
1PC	FRONT DOOR MIRROR ASSY N/S	<i>one</i>	680.50	\$1,062.50	—
1PC	FRONT DOOR MIRROR COVER N/S	<i>one</i>	145.10	\$165.50	—
1PC	FRONT DOOR GLASS N/S	<i>Replaced</i>	620.90	\$845.50	—
1PC	FRONT DOOR GLASS OUTER MOULDING N/S	<i>scr</i>	141.20	\$166.80	—
1PC	FRONT FENDER N/S	<i>11</i>		\$651.10	X
				\$4,080.30	

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	\$50.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$380.00	200
TO PUTTY & SPRAY PAINTING	\$500.00	300
TOTAL	\$5,060.30	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1832.90
252
1832.90
1832.90
20%
1575