

SCOPE OF WORK

- 1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

VEHICLE TYPE	AMBULANCE	REGISTRATION NO	QX 1293 L	REPAIR TYPE	ACCIDENT
MAKE/MODEL	MERCEDES BENZ	UNIT	STN 31	CONTRACTOR	INDECO

S/N	ITEM DESCRIPTION	PARTS					LABOUR		
		PARTS QTY	PARTS COST PER UNIT (\$)	MARK UP RATE	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	MAN-HOUR RATE (\$)	MAN-HOUR QTY	TOTAL MAN-HOUR COST (\$)
	SCOPE OF REPAIRS								
A	Labour								
1	Remove & replace bonnet sticker & wording							5	
2	Panel beat dented bonnet							3	
3	Putty & spray paint bonnet							3	
4	Spray lacquer over after putting up sticker & wording for bonnet							3	
5	Remove & replace front bumper retainer							0.5	
6	Remove & replace front dented bumper							3	
7	Remove & replace dented AP panel							1	
8	Remove & replace dented radiator grill							2	
9	Remove & replace R/H fender sticker							1	
10	Panel beat dented R/H fender							2	
11	Remove & replace front dented number plate							0.5	
12	Panel beat dented siren speaker bracket							2	
13	Remove & replace dislodged siren speaker							1	
14	Remove & replace dented power steering pipe							1	
15	Remove & replace air con motor fan							2	
16	Remove & replace air con condenser							2	
17	Remove & replace radiator							6	
18	Remove & replace radiator top & bottom hose							1	
19	Putty & spray paint AP panel & R/H fender							3	
	SUB TOTAL							42	
B	Materials								