


ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 30421

Date: 03.4.2021

Phua Li Choo

Blk 332 #11-253 Serangoon Ave 3

Singapore 550332.

Suzuki Vitara

Estimate Repair Cost for Vehicle Reg. No: SLG 7577 C

✓ 1 Pc. Front Bonnet	✓	1,020.00	✓
1 Pc. Front Bonnet Sponge	✓	498.00	✓
10 Pcs. Front Bonnet Sponge Clips	✓	60.00	✓ 15/- SH
2 Pcs. Front Bonnet Hinger	✓	296.00	X
1 Pc. Front Fog Lamp	✓	499.80	✓
RH 1 Pc. Front Fog Lamp Holder	✓	186.50	✓
1 Pc. Wiper Tank Assy.	✓	508.00	✓ 125.30
RH 1 Pc. Head Lamp	✓	2,499.05	✓ 2499.05
1 Pc. Head Lamp Module	✓	989.00	X
RH 1 Pcs. Head Lamp Bracket	✓	56.00	✓
1 Pc. Front Grille Assy.	✓	468.40	X
1 Pc. Front Grille Logo	✓	332.50	X
10 Pcs. Front Grille Clips	✓	60.00	X
1 Pc. Front Bumper	✓	998.80	✓ 998.80
1 Pc. Front Bumper Grille (CTR)	✓	189.20	X
1 Pc. Front Bumper Towing Cover	✓	26.00	✓
1 Pc. Front Bumper Lamp LED	✓	869.80	✓ 869.80
1 Pc. Front Bumper Corner Pad	✓	320.00	✓
1 Pc. Front Bumper Centre	✓	330.00	X
1 Pc. Front Bumper Lower	✓	180.90	X
12 Pcs. Front Bumper Clips	✓	72.00	✓ 30/- SH
1 Pc. Front Bumper Side Catch	✓	28.80	X
1 Pc. Front Bumper Retainer	✓	29.30	✓
1 Pc. Front Bumper Reinforcement	✓	729.85	✓ 729.85
1 Pc. Front RH Fender	✓	325.50	✓
1 Pc. Front RH Fender Garnish	✓	110.60	✓
10 Pcs. Front RH Fender Garnish Clips	✓	60.00	✓ 15/- SH
1 Pc. Front RH Fender Dust Cover	✓	127.50	✓
10 Pcs. Front RH Dust Cover Clips	✓	60.00	✓ 15/- SH
2 Pcs. Distance Sensor	✓	252.00	✓
1 Pc. Distance Harnes Wire	✓	288.00	X
1 Pc. Support Panel	✓	910.00	X
1 Pc Fender Top	✓	199.00	✓

Page 1 of 2

List 9077.00
10% 8169.30

SH 75.00



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



1 Pc. Coolant ~~HN~~

90.00 ~~X~~

Total (Panels / Parts): 13,471.50 (SGD)

LABOR CHARGES

To remove & refit wiring, checking & memory to standard Setting & refocus head lamp. 120.00 30/-

To repair, knocking, straightening all accident affected area. 900.00 800/-

To respray painting on all accident damage affected area. 1,200.00 800/-

To rust proof all accident affected area. 120.00 40/- 1670.00

To remove & refit radiator, fan motor assy & all affected Area. 180.00 HN

To remove & refit air-con condenser, pipe & top-up gas & oil. 280.00 HN

Total (Labor Charges): 2,800.00 (SGD)

P/P 9914.30

TOTAL COST SUMMARY

PANELS / PARTS 13,471.50
LABOR CHARGES 2,800.00

Grand Total: 16,271.50 (SGD)

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'Alfred Auto Services and Supplies'

Alfred Quah

ALFRED AUTO SERVICES & SUPPLIES

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Page 2 of 2

Dismantle
on 12/04/2021

06/04/2021 @ 1000hr
Not Andrus
P&T by P&T.

Photo after repair
with damaged parts.

Yea
LKK Andrus

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: 06/04/2021