



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2102846

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 23/04/2021
Reference CS3/III20008937/Gtf3e2-1
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SMK 7983E
Insured Veh. SH 9102M
Claim No. MCT20080305
Policy No. MCOM0015
Accident Date 20/08/2020
Inspection Date 25/08/2020

Description	Total
Survey Inspection	250.00
Digital Photographs	
Transportation	
Less: Pre-Repair Survey Fee (Invoice.AC2006049 dated 03/09/2020)	-120.00
Subtotal	130.00
GST (7%)	9.10
Grand Total	139.10

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM