



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL

INV No. AC2105103

50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWER
SINGAPORE 048623

INV Date 21/07/2021
Reference CS3/SMO21004365/EKqf3e
Code SMO

PROFESSIONAL SERVICE FEE

Vehicle No. SV 45E
Insured Veh. FS 998A
Claim No. CMTD2101038/SYH
Policy No. D21MTMC01000723
Accident Date 03/04/2021
Inspection Date 06/04/2021

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 07.04.2021)	10.00
Subtotal	110.00
GST (7%)	7.70
Grand Total	117.70

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM