



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA LOH			Ref: CC4/ASM21004366/Bga3q2 Date: 14/02/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 128A	Veh. Inspected	SKC 1542A
	Policy No.	P2413997	Coverage (\$)	0.00
	Claim No.	S1M0375Z	Excess (\$)	0.00
	Assign From		Assign Date	06/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALPHARD	c.c	2362
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	JTEGD21H508162741	Colour	BEIGE
	Odometer	276847 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 R19	GREENTRAC	6 mm
	L/H Front Tyre	245/40 R19	GREENTRAC	6 mm
	R/H Rear Tyre	245/40 R19	GUEST	6 mm
	L/H Rear Tyre	245/40 R19	GUEST	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	01/04/2021	Inspection Date	07/04/2021
	Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	