

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 19960	/198R GST Reg. No. 19-9	9607198-R	
		Affiliated to Federation Internatio	nale Des Experts En Aut	omobile	
	AUTO & GENERA	L INSURANCE (S) PL	Ref	f: CS/AGI21004370/Utf3n2	
		TINSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Dai	te: 12/04/2021	
			Co	de: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLE 1941J	Veh. Inspected	SLQ 9764M	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10009422/CH	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	06/04/2021	
2.		Vehicle Parti	culars & Condition		
	Make & Model	HYUNDAI ELANTRA (A)	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	KMHD841CMJU515812	Colour	RED	
	Odometer	76527 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	YOKOHAMA	7 mm	
	L/H Front Tyre	205/55 R16	YOKOHAMA	7 mm	
	R/H Rear Tyre	205/55 R16	YOKOHAMA	7 mm	
	L/H Rear Tyre	205/55 R16	YOKOHAMA	7 mm	
4.	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.  DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	14/03/2021	Inspection Date	07/04/2021	
	Survey held at	FOCUS AUTO PTE LTD	•		
		NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883			
5a.		Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	DJIN ACCORDANC	Estimate Days of Repair			
		=	<i>,</i>		

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: